


## Vehicle details

|                   |                    |              |                                                    |                           |               |
|-------------------|--------------------|--------------|----------------------------------------------------|---------------------------|---------------|
| VIN               | TMAJD812D NJ045872 | Brand        | HYUNDAI                                            | Maintenance date          | -             |
| Licence Plate     | N5-79-BR           | Model        | TUCSON 1.6 T-GDI PHEV Comfort Smart 4WD Automaa 5d | Maintenance mileage       | -             |
| Registration date | 22/10/2021         | Year         | 2021                                               | Exterior Color            | Grey Metallic |
| Odometer          | 67 986 km          | Engine size  | 1598                                               | interior Color            | Black         |
| Fuel              | Hybrid petrol      | Body Type    | -                                                  | Next technical inspection | -             |
| Seats             | -                  | Transmission | Automatic                                          | CO2                       | -             |
| Doors             | 5                  | Gears        | -                                                  |                           |               |

## Inspection Details

|                 |            |                 |              |
|-----------------|------------|-----------------|--------------|
| Inspection date | 23/10/2025 | Inspection loc. | Dekra Ayvens |
|-----------------|------------|-----------------|--------------|



## Generic equipment

|                            |   |
|----------------------------|---|
| Automated air-conditioning | ✓ |
| Cruise control             | ✓ |
| GPS system                 | ✓ |
| Alloy wheel rims           | ✓ |
| Automatic Gearbox          | ✓ |
| Heating seats              | ✓ |
| Metallic paint             | ✓ |
| Central locking            | ✓ |
| Electric windows           | ✓ |
| Side rails                 | ✓ |
| Park Distance Control      | ✓ |
| Audio System               | ✓ |
| Led lighting               | ✓ |

## Removable element


|                  |   |
|------------------|---|
| Spare wheel kit  | ✓ |
| Load cover       | ✓ |
| Vehicle charger  | ✓ |
| Wireless charger | ✓ |

## Technical Document

|                         |   |
|-------------------------|---|
| User manual             | ✓ |
| Warranty booklet        | ✓ |
| Spare key               | ✓ |
| Remote key              | ✓ |
| Sat Nav CD ROM Software | ✓ |

## Tyres

Pirelli 235/50/19 Summer 7.0 mm



Pirelli 235/50/19 Summer 7.0 mm



Pirelli 235/50/19 Summer 5.5 mm

Pirelli 235/50/19 Summer 5.0 mm


## Exterior

6



|             |                  |
|-------------|------------------|
| Part        | Wing             |
| Position    | Back right       |
| Damages     | Chemical deposit |
| Severity    | -                |
| Repair mode | Lumpsum repair   |

7



|             |              |
|-------------|--------------|
| Part        | Door         |
| Position    | Front right  |
| Damages     | Dent & Chips |
| Severity    | -            |
| Repair mode | Repair       |

8



|             |                    |
|-------------|--------------------|
| Part        | Wing               |
| Position    | Front right        |
| Damages     | Dented             |
| Severity    | Diameter (mm) > 20 |
| Repair mode | Smart Repair       |

9



|             |           |
|-------------|-----------|
| Part        | Bumper    |
| Position    | Front     |
| Damages     | Scratched |
| Severity    | -         |
| Repair mode | Repair    |

10



|             |              |
|-------------|--------------|
| Part        | Windscreen   |
| Position    | -            |
| Damages     | Stone impact |
| Severity    | -            |
| Repair mode | For info     |

## Interior damage

1



|             |                   |
|-------------|-------------------|
| Part        | Interior cleaning |
| Position    | Front             |
| Damages     | Stained/dirty     |
| Severity    | -                 |
| Repair mode | Cleaning          |

2



|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Up                       |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |

3



|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Down                     |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |

4



|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Back right               |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |

5



|             |                          |
|-------------|--------------------------|
| Part        | Interior tailgate lining |
| Position    | Back left                |
| Damages     | Scratched                |
| Severity    | -                        |
| Repair mode | Replace                  |