



Hyundai Tucson: S856LF

Vinnnummer:	TMAJD812DPJ165148	Versionname:	Tucson 1.6 T-GDI 195kW 4WD PHEV Comfort Smart automaat
First Registrationdate:	24/02/2023	Fiscalpower:	
Expertise Mileage:	80705	Power Kw:	132
Bodytype:		Body colour:	Phantom Black mica
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Hybrid Petrol	Parking lot:	506
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Central consol F
Autom climate control		Luggage cover
Windows electric F		Headlights Xenon/LED/Laser
Radio multimedia		Front parking sensors
		Rear parking sensors

Degree of wear

	235/50/19/103 V			
Summer tyres:	Fr.L.	Michelin: 3,7 mm	Fr.R.	Michelin: 4,7 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4,6 mm
Tyre profile depth FL				3.7
Tyre profile depth FR				4.7
Tyre profile depth RL				4.0
Tyre profile depth RR				4.6
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	1

Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Charging cable (normal), Missing, Replace



Boot lid covering R, Scratch(es), Replace



Bumper R, Scratch(es), Smart repair



Bumper trim R, Scratch(es), Replace



Roof, Chemical polution, Polish

