


Vehicle details

VIN	TMAJD81BA NJ242070	Brand	HYUNDAI	Maintenance date	01/01/1900
Licence Plate	R6-67-PR	Model	TUCSON 1.6 T-GDI 48V MHEV Comfort Smart 5d	Maintenance mileage	-
Registration date	31/10/2022	Year	2022	Exterior Color	White Solid
Odometer	51 454 km	Engine size	1598	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	6		

Inspection Details

Inspection date	26/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Tow	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Michelin 215/65/17 Summer 4.0 mm



Michelin 215/65/17 Summer 4.0 mm



Michelin 215/65/17 Summer 4.5 mm



Michelin 215/65/17 Summer 4.5 mm

Exterior

3



Part	Bumper
Position	Front right
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

4



Part	Bonnet
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

6



Part	Unpainted bumper
Position	Back
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

Interior damage

1



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace

2



Part	Interior tailgate lining
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Replace

5



Part	Interior tailgate lining
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Replace

Comments

Opslagpark : Dekra Ayvens