



# HYUNDAI ix35

## ix35 1.7 CRDi 115 2WD Blue Drive Pack Business

VIN NO TMAJU81UAEJ565799  
Registration Number DG023VQ



|              |                      |                         |                          |
|--------------|----------------------|-------------------------|--------------------------|
| MOT Date     | Number of Owners     | Number of Keys          | Odometer Reading         |
| -            | -                    | 2                       | 142941 km                |
| Last Service | Last Service Mileage | First Registration Date | Country First Registered |
| -            | -                    | 2014-05-13              | -                        |

### Inspection Report Summary

|                         |                             |                |                 |
|-------------------------|-----------------------------|----------------|-----------------|
| Customer                | BCAuto Encheres             | Report Number  | P20251009102842 |
| Inspection Date / Place | 2025-10-09 / BCA MONTMARTIN | Cosmetic Grade | 1               |

### Vehicle Summary

|                   |                       |                        |             |
|-------------------|-----------------------|------------------------|-------------|
| Vehicle Condition | Non-Runner            | VAT Type               | Exempt Rate |
| Fuel Type         | Diesel                | Gearbox Type           | Manual      |
| Colour            | White                 | Engine Size (cc)       | 1685        |
| Engine Size       | 1.7                   | No of Doors            | 5           |
| Body Type         | Stationwagon / Estate | Drive Train            | Front       |
| Seat Colour       |                       | No of Seats            | 5           |
| Charging Cables   |                       | NEDC CO2 Rating (q/km) | 135         |
| Engine Rating CV  | 6                     | Metalic Colour         | No          |
| Accident Damage   | No                    | Euro Emission          |             |

### Vehicle History & Documents

|                        |            |                      |     |
|------------------------|------------|----------------------|-----|
| Service Book Available | Present    | Next Service Mileage | km  |
| Previous Usage         | Normal Use | Imported             | Yes |
| Manufacturer Warrenty  |            |                      |     |





Equipment

|                   |                |                                   |                      |
|-------------------|----------------|-----------------------------------|----------------------|
| Central locking   | Radio          | Alloys wheels                     | Tow ball             |
| Front fog lamps   | Roof rails     | Electrically folding wing mirrors | Rear parking sensors |
| Stability control | Cruise control | Power assisted steering           | Satellite navigation |


Equipment Details

|              |       |                  |     |
|--------------|-------|------------------|-----|
| Seat Heating | Front | Air Conditioning | Yes |
|--------------|-------|------------------|-----|




Cosmetic Damage

5 Dommages



3 Dommages



| Component                    | Damage                    | Comments |
|------------------------------|---------------------------|----------|
| 1 Floor Carpet               | Interior / Dirty          |          |
| 2 Tailgate                   | Paint / Scratch / Line    |          |
| 3 Rim / Back Right           | Out of Bodywork / Scratch |          |
| 4 Rim / Front Right          | Out of Bodywork / Scratch |          |
| 5 Rim / Back Left            | Out of Bodywork / Scratch |          |
| 6 Rim / Front Left           | Out of Bodywork / Scratch |          |
| 7 Tailgate Upholstery / Back | Interior / Scratched      |          |
| 8 Seat Cushion / Front Left  | Interior / Worn - out     |          |



1. Floor Carpet  
Interior / Dirty -



2. Tailgate  
Paint / Scratch / Line -



3. Rim / Back Right  
Out of Bodywork / Scratch -



4. Rim / Front Right  
Out of Bodywork / Scratch -



5. Rim / Back Left  
Out of Bodywork / Scratch -



6. Rim / Front Left  
Out of Bodywork / Scratch -





7. Tailgate Upholstery / Back  
Interior / Scratched -



8. Seat Cushion / Front Left  
Interior / Worn - out -

Mechanical Condition

Tyres

Presence Anti-Theft Lock Nut 

 *No troubles detected, good condition or correct tests, according to vehicle age and mileage*

 *Damages or malfunction detected that requires repairs by the buyer*

 *Not applicable*

 *Not tested*

Disclaimer Section

*The test drive is done on a flat surface and lasts about 2 minutes. The driven distance is a minimum of 300 meters, including a u-turn, an acceleration and a braking phase. The highest speed achieved during this test is 50km/h. The mechanical check is a visual and dynamic diagnosis without any disassembly. We cannot guarantee any mechanical wear part.*