

Vehicle details

VIN	TMAK281GF LJ002716	Brand	HYUNDAI	Maintenance date	-
Licence Plate	H1-85-RP	Model	KONA Comfort Electric 64 kWh 5d	Maintenance mileage	-
Registration date	20/05/2020	Year	2020	Exterior Color	White Solid
Odometer	104 003 km	Engine size	-	interior Color	Black
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	28/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓


Removable element

Spare wheel kit	✓
Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 215/55/17 Summer 4.0 mm		Michelin 215/55/17 Summer 3.0 mm	
Michelin 215/55/17 Summer 5.0 mm		Michelin 215/55/17 Summer 5.0 mm	

Exterior

4



●●●●

Part	Door
Position	Front right
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

5



●●

Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

6



●●

Part	Roof
Position	-
Damages	Chemical deposit
Severity	-
Repair mode	Lumpsum repair

7



●●

Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

8



●●

Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

Interior damage

1



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2



Part	Interior tailgate lining
Position	-
Damages	Scratched
Severity	-
Repair mode	Smart Repair

3



Part	Boot carpet
Position	Right
Damages	Scratched
Severity	-
Repair mode	Smart Repair