


Vehicle details

VIN	TMAK281GF LJ013479	Brand	HYUNDAI	Maintenance date	-
Licence Plate	J3-31-KF	Model	KONA Comfort Electric 64 kWh	Maintenance mileage	-
Registration date	31/08/2020	Year	2020	Exterior Color	White Solid
Odometer	131 105 km	Engine size	-	interior Color	Grey
Fuel	Electric	Body Type	-	Next technical inspection	-
Seats	5	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	29/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Electric seats	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Rear parcel shelf	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 215/55/17 Summer 3.5 mm	Michelin 215/55/17 Summer 7.5 mm
Michelin 215/55/17 Summer 6.5 mm	Michelin 215/55/17 Summer 6.5 mm

Exterior

1



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

2



Part	Wing moulding
Position	Back left
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

3



Part	Bumper
Position	Back left
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

5



Part	Door
Position	Front right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

6



Part	Alloy wheel 17"
Position	Front right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

7



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair