



## Hyundai Kona: J127XB

|                         |                          |                        |                                                     |
|-------------------------|--------------------------|------------------------|-----------------------------------------------------|
| Vinnumber:              | <b>TMAK281GFLJ017295</b> | Versionname:           | <b>Kona EV 150kW / 64kWh Comfort Smart automaat</b> |
| First Registrationdate: | <b>16/12/2020</b>        | Fiscalpower:           |                                                     |
| Expertise Mileage:      | <b>174050</b>            | Power Kw:              | <b>150</b>                                          |
| Bodytype:               |                          | Body colour            | <b>Polar White</b>                                  |
| Gearbox:                | <b>Automatic</b>         | Paint type             | <b>Opaque</b>                                       |
| Transmission:           | <b>Front</b>             | Type of rims (mounted) | <b>Aluminium</b>                                    |
| Fueltype:               | <b>Electric</b>          | Parking lot            | <b>195</b>                                          |
| Number of seats         | <b>5</b>                 |                        |                                                     |
| Type of rims (mounted)  | <b>Aluminium</b>         |                        |                                                     |
| Maintenance needed      | <b>No</b>                |                        |                                                     |

## Options

|                       |          |                      |
|-----------------------|----------|----------------------|
| Number of keys total  | <b>2</b> | Telephone equipment  |
| GPS                   |          | Central consol F     |
| Autom climate control |          | Luggage cover        |
| Windows electric F    |          | Rear parking sensors |
| Radio multimedia      |          |                      |


## Tyres

| Location | Position | Measures                           | Depth  | Make    | Type   |
|----------|----------|------------------------------------|--------|---------|--------|
| Front    | Left     | 215 / 55 / 17 / 94 / W / Aluminium | 7,2 mm | Hankook | Summer |
|          | Right    | 215 / 55 / 17 / 94 / W / Aluminium | 6,3 mm | Hankook | Summer |
| Rear     | Left     | 215 / 55 / 17 / 94 / W / Aluminium | 6,7 mm | Hankook | Summer |
|          | Right    | 215 / 55 / 17 / 94 / W / Aluminium | 6,1 mm | Hankook | Summer |

## Assistance equipment

|                                          |          |
|------------------------------------------|----------|
| Number of charging cables (normal)       | <b>1</b> |
| Number of charging cables (rapid charge) | <b>1</b> |

## Roof liner, Stain, Cleaning



## Interior, Stain, Cleaning



## Door FL, Bad repair, Repair and paint (complete)



## Wing RL, Scratch(es), Repair and paint (complete)



Door RL, Scratch(es), Repair and paint (complete)



Windscreen, Stone chip(s), Windscreen repair



Bonnet, Stone chip(s), Repair and paint (complete)



Bumper moulding F, Scratch(es), Replace and paint



Door RR, Dent(s), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Rust, Repair and paint (complete)



Bodywork, Chemical polution, Polish

