



Hyundai Kona: J384JX

Vinnnummer:	TMAK581GFLJ003637	Versionname:	Actie: Kona EV (2020) 150kW / 64kWh 2WD Premium automaat
First Registrationdate:	1/10/2020	Fiscalpower:	
Expertise Mileage:	142984	Power Kw:	150
Bodytype:		Body colour:	Dark Knight Mica Parelmoer
Gearbox:	Automatic	Paint type:	Metallic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Electric	Parking lot:	362
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining leather
Autom climate control		Central consol F
Windows electric F		Luggage cover
Radio multimedia		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Tow bar removable

Degree of wear

205/55/17/91 H				
Winter tyres:	Fr.L.	Vredestein: 4,6 mm	Fr.R.	Vredestein: 5,2 mm
	Re.L.	Vredestein: 6,9 mm	Re.R.	Vredestein: 6,5 mm
Tyre profile depth FL				4.6
Tyre profile depth FR				5.2
Tyre profile depth RL				6.9
Tyre profile depth RR				6.5
Tyre size FL				205/55 R 17 91 H
Tyre size FR				205/55 R 17 91 H
Tyre size RL				205/55 R 17 91 H
Tyre size RR				205/55 R 17 91 H
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				2480
Tyre make FR				2480
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	1
Number of charging cables (rapid charge)	1

Outside rear-view mirror housing L, Scratch(es), Replace and paint



Door FL, Scratch(es), Repair and paint (complete)



Wing FL, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Bumper moulding FR, Scratch(es), Replace and paint




Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Internal boot lining L, Scratch(es), Replace



Internal boot lining R, Scratch(es), Replace



Rear window, Scratch(es), Replace

