



status report

Report number:	0000000782496-EN926	Off. Mark :	NE-SP 921E
reference number:	30774638		

Vehicle Data

Hyundai Kona (OS)(2017->) Premium Elektro 2WD

Vehicle identification number .:	TMAK581GFLJ016716	mileage read:	22330 km
First Registration / construction Year:	23.07.2021 / 2020	Inspection date/place:	13.08.2024 10:47 41464 Neuss
Bodywork:	SUV	Body type:	hatchback
fuel:	Electric	Transmission type:	Automatic
GPS sat nav disk:	Hard Disk Drive	Displacement / power:	0 ccm / 150 kW (204 PS)
Engine:	front-wheel drive	Paint:	Stellar Blue / MET
Type of paint:	Metallic	Doors / seats:	5 / 5
Number of keys:	2	Next HU / AU:	2024-07 / 2024-07
cushion type:	imitation leather	Service book available:	Yes
Interior Color:	Black	Maintained service book:	No
smoking vehicle:	No	Last service km / on the:	17270 / 2023-07-25
Vehicle roadworthy:	Yes	Submitted vehicle documents:	Registration Certificate
State outside:	2 - Good	condition inside:	2 - Good

The status Report was created impartially and to the best of my knowledge. The images listed in the status Report are part of the vehicle description regarding the equipment and the vehicle condition.





Mounted tires

	Summer tires	Aluminium original
Tyre / wheel type:		
1st axis - Left / states .	Michelin	215/-R17/-- 4 mm
1st axis - right / states .	Michelin	215/-R17/-- 4 mm
2nd axis - Left / states .	Michelin	215/-R17/-- 4 mm
2nd axis - right / states .	Michelin	215/-R17/-- 4 mm
Traffic Safety:	Roadworthy	

Series

- 3rd brake light
- Airbag passenger side
- Airbag driver side
- Anti-lock braking system (ABS)
- Outside mirror electr. adjustable and heated, both
- Flashing light integrated in the exterior mirror
- Roof rails
- Electr. Brake force distribution
- Electron. Stability control (ESC) with brake assistant
- Fahrassistenz-System: aktiver Spurhalteassistent (LKAS, Lane Keep Assist System)
- Driving assistance system: Autonomous emergency braking function including front collision warning (FCA)
- Driver assistance system: high beam assistant
- Fahrassistenz-System: Stauassistent
- Driver information system (7.0 inch display)
- Electric window lift at the front
- Windscreen with band filter on top
- Countersteering support (Vehicle Stability Management, VSM)
- Luggage net in the luggage / loading space
- Cruise control system (tempomat) with distance control ACC
- Cup holder in front
- Rear window heatable
- Interior mirror with automatic dimming
- Body: 5-door
- Head airbag system
- Cornering
- Airbag front passenger side can be switched off
- Alarm system
- Drive type: front-wheel drive
- Exterior mirror painted
- Brake Assist
- Automatic switch-on for driving lights / light sensor
- Electric motor 150 kW (cont. 28 kW)
- Driving Assistance package
- Fahrassistenz-System: Aufmerksamkeits-Assistent
- Driver assistance system: hill start assist
- Fahrassistenz-System: Sicherheitssystem mit automatischem Notruf (ERA GLONASS / eCall)
- Driver assistance system: traffic sign assistant
- Electric window rear
- Handsfree Bluetooth
- Frontscheibe wärmedämmend
- Gepäck-/Laderaumleuchte
- Luggage compartment cover / roller blind
- Getriebe für Elektrofahrzeug
- Taillights LED
- Induction charger for smartphone
- Isofix seats for child seat
- Climate
- Headrests adjustable at the back

- Kühlergrill Wagenfarbe
- Lumbar support seat front left, electr. adjustable
- Lenkrad heizbar
- Reading light
- LM rims
- Navigations-Paket
- Premium-Paket
- Radstand 2600 mm
- Tire pressure monitoring system
- Rear seat back divided / foldable
- Window fogging detection / control
- Scheinwerfer Voll-LED
- Darkened side windows from the B-pillar
- Seat front left electr. adjustable
- Seat front right electr. adjustable
- Sitzbezug / Polsterung: Stoff/Leder
- Smart key
- Sun visors with mirror (illuminated)
- Start / Stop system
- Door handles outside body color
- USB port + AUX-IN port
- Immobilizer (electronic)
- Central locking with remote control
- Charging cable with Type 2 plug
- Steering wheel (leather) with multifunction
- Steering wheel with paddle shifters
- Headlamp leveling
- Center armrest front with compartment
- Parking brake electric (EPB)
- Radio reception digital (DAB +)
- Tire repair kit
- Backup camera
- Shift / selector lever handle leather
- Rain-sensing wipers
- Side airbag in front
- Power steering
- Seat front left height adjustable
- Seat front right height adjustable
- Heated seats in the front
- Sonderlackierung Galaxy Gray Metallic
- Start-stop button
- Daytime running light LED
- Türgriffe innen verchromt
- Glazed tinted
- Heat pump for heating/air conditioning

Special Features

- Metallic paint
- Seat package
seat heating on the back, Seat cover / upholstery: leather, Comfort seats in front including ventilation

We remind you that the data provided were taken from the DAT database. No liability can be assumed for the completeness and correctness.

General exam

test drive:

Conducted limited

Because of the conditions a short test drive could be performed only at a moderate speed .
As part of the test drive further tests were carried out. The results are documented later in the report .

Subfloor Inspection:	Not performed A visit to the underbody of the car was not performed .
Mileage plausible:	Not testable Not testable
reference:	
Note Road Safe:	

Accident claims investigation	
Rep. Predamages / -height gross:	
Layers of paint thickness measurement:	
Existing collision damage:	Not established On the vehicle body shell were on visual examination found no existing accident damages (other than the usual signs of use) .
reference:	

Overview of technical examination					
Air conditioning:	Examined limited	✘	Lighting system:	examined limited	✘
Sunroof / convertible:	unavailable	✘	Seat heating:	Examined limited	✘
Brake system:	examined limited	✘	Engine running:	examined limited	✘

Implemented technical examination	
air conditioning:	The air conditioning system could be tested only restricted during the visit .
lighting system:	The Lichtenlange could be considered limited to the tour date .
Sunroof / convertible:	unavailable
Seat heating:	Examined limited
brake system:	The braking system has been tested by a visual inspection .
engine running:	Checking the engine running was limited. Here no audible or visual abnormalities were noted .
reference:	*Serviceintervall nach Herstellervorgaben überzogen (12 Monate / 15.000 km) Verlust der Herstellergarantie und jeglicher Kulanz.

Damage			
	Exterior and Styling		
	Component	Damage	Rep kind
1.	Rim front - left	Deep scratch	Smart repair
2.	Hood	Wear and tear	Without repair
3.	Rear Door - Right	Wear and tear	Without repair
4.	Rim rear - right	Wear and tear	Without repair
5.	Rear Bumper	Deep scratch	Condition/polish
6.	Windshield	Wear and tear	Without repair



Others

	Component	Damage	Rep kind
7.	Herstellergarantie	Not looked after	
8.	maintenance	Due	Replace
9.	safety vest	Missing	Replace
10.	first aid kit	Missing	Replace

A Pre Damage check is being made solely in the context and the possibilities of a visual inspection and measurement of paint layers without a Disassembly of components. A possible existence of pre-damages is unknown.

The expert points out that the vehicle in addition to the age- damage listed in the report and may have a high mileage - related wear , as in normal use are inevitable (small bumps , dents , scratches) .

There shall be no liability accepted for any defect and / or remained hidden damage in terms of electronics and mechanics, as well as for fraudulent misrepresentation and concealed defects .



Photo documentation



front Left



front Right



rear Left



rear Right



Inside



trunk



instrument cluster



mileage



center console




rims




engine compartment




key



Service book / proof



Service book / proof



Service book / proof



Others



tires



tires



tires



tires



1. Rim front - left
Deep scratch - Smart repair



1. Rim front - left
Deep scratch - Smart repair



2. Hood
Wear and tear - Without repair



3. Rear Door - Right
Wear and tear - Without repair



3. Rear Door - Right
Wear and tear - Without repair



4. Rim rear - right
Wear and tear - Without repair



4. Rim rear - right
Wear and tear - Without repair



5. Rear Bumper
Deep scratch - Condition/polish



5. Rear Bumper
Deep scratch - Condition/polish



6. Windshield
Wear and tear - Without repair



6. Windshield
Wear and tear - Without repair