



Skoda Superb (KKL): 1XCF714

Vinnumber:	TMBAG7NP2L7030448	Versionname:	Superb Style 1.6TDi 120pk/cv 5p DSG7
First Registrationdate:	14/11/2019	Fiscalpower:	
Expertise Mileage:	116218	Power Kw:	88
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/55/17/94 V			
Summer tyres:	Fr.L.	Pirelli: 4 mm	Fr.R.	Pirelli: 4 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				264
Tyre make FR				264
Tyre make RL				264
Tyre make RR				264

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Spot repair



Windscreen, Stone chip(s), Windscreen repair



Outside rear-view mirror housing L, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Tailgate / Boot, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Step R, Dent(s), Acceptable



Wing RR, Scratch(es), Acceptable



Door RR, Scratch(es), Acceptable



Door FR, Scratch(es), Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable

