



SKODA Superb Superb 2.0 TDI DSG

VIN NO TMBAJ7NP3F7007329
Registration Number P3F7007329



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	160092 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2024-10-15	144953	2015-06-12	-

Inspection Report Summary

Customer	BCA Online	Report Number	P20251001113922
Inspection Date / Place	2025-10-01 / Extern	Cosmetic Grade	3

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Braun	Seat Covering	Synthetic Leather
Charging Cables		NEDC CO2 Rating (q/km)	122
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Computer Print Out Available	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

Tow ball	USB Socket	Alloys wheels	Anti-lock braking
Bi Xenon Headlamps	Cruise control	Digital Radio	Front fog lamps
Heated wing mirrors	Remote central locking	Stability control	Electrically folding wing mirrors
Leather steering wheel	Rear parking sensors	Trip Computer	Airbag Status
Ambientlighting	Auxiliary Socket	Bluetooth telephone interface	Diesel particulate filter
Enhanced speaker system	Front parking sensors	Remote adjusting wing mirrors	Satellite navigation
CD Player	Electrictailgate	Radio	

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Three Zone Climate Control
Alloy Wheel Size	19	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	3	Left Rear Tyre Depth	3

Cosmetic Damage

8 Schäden




0 Schäden



Component		Damage	Comments
1	Roof	Bodywork / Dent / Hail Area	
2	Hood	Bodywork / Dent / Dent	
3	Windshield / Front	Glass Break / Impact	
4	Bumper / Front	Paint / Scratch / Scuff	
5	Fender / Back Left	Bodywork / Dent / Dent	
6	Other	Paint / Scratch / Scuff	
7	Bumper / Back	Bodywork / Dent / Dent	
8	Door / Front Right	Bodywork / Dent / Dent	



1. Roof
Bodywork / Dent / Hail Area -




2. Hood
Bodywork / Dent / Dent -



3. Windshield / Front
Glass Break / Impact -




4. Bumper / Front
Paint / Scratch / Scuff -



5. Fender / Back Left
Bodywork / Dent / Dent -



6.
Paint / Scratch / Scuff -



7. Bumper / Back
Bodywork / Dent / Dent -



8. Door / Front Right
Bodywork / Dent / Dent -

Mechanical Condition

Equipments Test

Central Locking	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Navigation System	✓
Parking Sensors / Cameras Functioning	✓	Other Equipments	✓

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Service Light	!
Tire Pressure Monitoring System	✓	Display Defect	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✔	
Engine			
Engine Noise	✔	The Gears Scratch / Skip / Abnormal Operation	!
Fume Quantity	✔	Power Loss	✔
Brake			
Brake System Anomaly		✔	
General			
Test Driven Status		NA	
✔ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)