



SKODA Fabia

Fabia 1.0 MPI

VIN NO TMBEA6NJ2JZ186810

Registration Number J2JZ186810



MOT Date

2026-07-01

Last Service

2022-04-06

Number of Owners

2

Last Service Mileage

67903

Number of Keys

2

First Registration Date

2018-06-28

Odometer Reading

136500 km

Country First Registered

Germany

Inspection Report Summary


Customer	BCA Online	Report Number	P20250925121906
Inspection Date / Place	2025-09-25 / ARS Altmann AG Riedstadt	Cosmetic Grade	5

Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	999
Engine Size	1.0	No of Doors	5
Body Type	Sedan	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	108
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warranty			







Equipment

Trip Computer	Airbag Status	Auxiliary Socket	Heated wing mirrors
Remote central locking	Radio	USB Socket	Anti-lock braking
Bluetooth telephone interface	Remote adjusting wing mirrors	Stability control	

Equipment Details


Air Conditioning	Yes	Seat Heating	No
------------------	-----	--------------	----

Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

21 Schäden




0 Schäden



Component		Damage	Comments
1	Hood	Bodywork / Dent / Hail Area	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Fender / Front Left	Bodywork / Dent / Hail Area	
4	Door / Front Left	Bodywork / Dent / Hail Area	
5	Deflector / Front Left	Bodywork / Dent	
6	Roof	Bodywork / Dent / Hail Area	
7	Pillar / Front Left	Bodywork / Dent / Dent	
8	Door / Back Left	Bodywork / Dent / Dent	
9	Pillar / Back Left	Bodywork / Dent / Dent	
10	Side Panel / Back Left	Bodywork / Dent / Hail Area	
11	Tailgate	Bodywork / Dent / Hail Area	
12	Bumper / Back	Bodywork / Dent / Dent	

13	Bumper / Back	Bodywork / Dent / Dent
14	Rear Window / Back	Glass Break / Scratch / Scratch
15	Bumper / Back	Paint / Scratch / Scuff
16	Fender / Back Right	Bodywork / Dent / Dent
17	Hubcap / Back Right	Missing element hubcap
18	Pillar / Back Right	Paint / Scratch / Scuff
19	Door / Back Right	Bodywork / Dent / Dent
20	Fender / Front Right	Bodywork / Dent / Dent
21	Fender / Front Right	Paint / Scratch / Scuff




1. Hood
Bodywork / Dent / Hail Area -



2. Bumper / Front
Paint / Scratch / Scuff -




3. Fender / Front Left
Bodywork / Dent / Hail Area -



4. Door / Front Left
Bodywork / Dent / Hail Area -




5. Deflector / Front Left
Bodywork / Dent -



6. Roof
Bodywork / Dent / Hail Area -




7. Pillar / Front Left
Bodywork / Dent / Dent -



8. Door / Back Left
Bodywork / Dent / Dent -



9. Pillar / Back Left
Bodywork / Dent / Dent -



10. Side Panel / Back Left
Bodywork / Dent / Hail Area -




11. Tailgate
Bodywork / Dent / Hail Area -



12. Bumper / Back
Bodywork / Dent / Dent -



13. Bumper / Back
Bodywork / Dent / Dent -



14. Rear Window / Back
Glass Break / Scratch / Scratch -



15. Bumper / Back
Paint / Scratch / Scuff -




16. Fender / Back Right
Bodywork / Dent / Dent -



17. Hubcap / Back Right
Missing element hubcap -



18. Pillar / Back Right
Paint / Scratch / Scuff -



19. Door / Back Right
Bodywork / Dent / Dent -



20. Fender / Front Right
Bodywork / Dent / Dent -



21. Fender / Front Right
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓

Equipments Test

Other Equipments	✓	Central Locking	✓
Main & Spare Keys Functioning	✓	Electric Windows	✓
AC / Heating System	✓		

Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Clutch

Clutch Functioning

Brake

Brake System Anomaly

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)