



Skoda Kamiq (UKL): 1YRT849

Vinnumber:	TMBGG6NW9M3053441	Versionname:	Kamiq Monte Carlo 1.6TDi 115pk/cv 5p DSG7
First Registrationdate:	20/11/2020	Fiscalpower:	
Expertise Mileage:	128516	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	29900.0		
Maintenance	710 dagen		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/45/18/93 V				
Winter tyres:	Fr.L.	Dunlop: 8 mm	Fr.R.	Dunlop: 5 mm
	Re.L.	Dunlop: 7 mm	Re.R.	Dunlop: 6 mm
Tyre profile depth FL				8.0
Tyre profile depth FR				5.0
Tyre profile depth RL				7.0
Tyre profile depth RR				6.0
Tyre size FL				215/45 R 18 93 V
Tyre size FR				215/45 R 18 93 V
Tyre size RL				215/45 R 18 93 V
Tyre size RR				215/45 R 18 93 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Instrument panel, complete, Not functioning (well), Check



Floor covering FL, Worn, Check



Seat cover FL, Stain, Acceptable



Interior covering A pillar L, Scratch(es), Acceptable



Interior covering A pillar R, Scratch(es), Acceptable



Seat cover FR, Stain, Acceptable



Alloy rim FL polished, Scratch(es), Acceptable



Step L, Dent(s), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Internal boot lining L, Scratch(es), Acceptable



Boot carpet, Stain, Acceptable





Rear bulkhead lining, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Tyre FR, Tear, Acceptable

