



SKODA Kamiq: 1XSS573

|                                   |                   |                        |                                             |
|-----------------------------------|-------------------|------------------------|---------------------------------------------|
| Vinnumber:                        | TMBGP6NW1L3088683 | Versionname:           | Kamiq 1.0 TSI Ambition 70kW/95pk 5D/P Man-5 |
| First Registrationdate:           | 7/05/2020         | Fiscalpower:           |                                             |
| Expertise Mileage:                | 71924             | Power Kw:              |                                             |
| Bodytype:                         |                   | Body colour            | Black                                       |
| Gearbox:                          | MAN 5 VIT         | Type of rims (mounted) | Aluminium                                   |
| Transmission:                     | Front             | Parking lot            | a222                                        |
| Fueltype:                         | Petrol            |                        |                                             |
| Number of doors                   | 5                 |                        |                                             |
| Number of seats                   | 5                 |                        |                                             |
| Number head rests                 | 5                 |                        |                                             |
| Type of rims (mounted)            | Aluminium         |                        |                                             |
| Certificate of Conformity         | Yes               |                        |                                             |
| Category                          | Passenger Car     |                        |                                             |
| Registration Certificate Car (BE) | Yes               |                        |                                             |
| Bodywork                          | Clean             |                        |                                             |
| Interior                          | Clean             |                        |                                             |

Options

|                                |   |                       |
|--------------------------------|---|-----------------------|
| Number of keys total           | 2 | Radio                 |
| Number keys remote             | 2 | Front parking sensors |
| Windows electric F             |   | Rear parking sensors  |
| Windows electric R             |   |                       |
| Cruise Control                 |   |                       |
| Steering wheel multifunctional |   |                       |
| Seats F heated                 |   |                       |
| Alarm                          |   |                       |
| Navigation with screen         |   |                       |
| Airco electronic               |   |                       |
| Rims alloy                     |   |                       |

Limited Technical Inspection

|                     |    |              |    |
|---------------------|----|--------------|----|
| Idle position       | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test  | OK |
| Exhaust gass        | OK | Transmission | OK |

Degree of wear

|                       |       |                   |       |                   |
|-----------------------|-------|-------------------|-------|-------------------|
| 205/55/17/95 H        |       |                   |       |                   |
| Winter tyres:         | Fr.L. | Michelin: 4 mm    | Fr.R. | Michelin: 4 mm    |
|                       | Re.L. | Continental: 5 mm | Re.R. | Continental: 5 mm |
| Tyre profile depth FL |       |                   |       | 4.0               |
| Tyre profile depth FR |       |                   |       | 4.0               |
| Tyre profile depth RL |       |                   |       | 5.0               |
| Tyre profile depth RR |       |                   |       | 5.0               |
| Tyre size FL          |       |                   |       | 205/55 R 17 95 H  |
| Tyre size FR          |       |                   |       | 205/55 R 17 95 H  |
| Tyre size RL          |       |                   |       | 205/55 R 17 95 V  |
| Tyre size RR          |       |                   |       | 205/55 R 17 95 V  |
| Tyre type FL          |       |                   |       | Winter            |
| Tyre type FR          |       |                   |       | Winter            |
| Tyre type RL          |       |                   |       | Winter            |
| Tyre type RR          |       |                   |       | Winter            |
| Tyre make FL          |       |                   |       | 261               |
| Tyre make FR          |       |                   |       | 261               |
| Tyre make RL          |       |                   |       | 256               |
| Tyre make RR          |       |                   |       | 256               |


Assistance equipment

|                       |     |      |     |
|-----------------------|-----|------|-----|
| Emergency spare wheel | Yes | Jack | Yes |
|-----------------------|-----|------|-----|

number of charging cables (normal)  
Number of charging cables (rapid charge)

0  
0

Roof liner, Scratch(es), Smart repair



Backrest cover RL, Scratch(es), Acceptable



Dashboard, Scratch(es), Acceptable



Glove box, Scratch(es), Acceptable



Door panel FR, Scratch(es), Smart repair



Headrest RM, Stain, Check



Bumper F, Scratch(es), Repair and paint (complete)




Bumper spoiler F, Scratch(es), Smart repair



Bonnet, Dent(s), Paintless dent repair



Windscreen, Stone chip(s), Acceptable




Alloy rim RL, Scratch(es), Acceptable



Step L, Dent(s) and scratch(es), Acceptable



Wing RL, Bad repair, Check



Door RL, Bad repair, Check



Outer door handle RL, Scratch(es), Acceptable




Door FL, Bad repair, Check






Outer sill L, Scratch(es), Polish



Outside rear-view mirror housing L, Bad repair, Check



Wing FL, Bad repair, Check



Luggage compartment cover, Missing, Check




Internal boot lining L, Scratch(es), Acceptable



Interior covering C pillar R, Scratch(es), Acceptable




Boot lid covering R, Scratch(es), Smart repair



Bumper R, Dent(s) and scratch(es), Spot repair






Bumper moulding R, Scratch(es), Smart repair



Tailgate / Boot, Dent(s), Spot repair



Rear spoiler, Scratch(es), Polish



Alloy rim FR, Scratch(es), Repair and paint (complete)




Tyre FR, Tear, Replace




Wing FR, Dent(s), Paintless dent repair



Outside rear-view mirror housing R, Scratch(es), Acceptable



Outside rear-view mirror base R, Scratch(es), Smart repair




Step R, Dent(s), Paintless dent repair




Outer sill R, Dent(s), Paintless dent repair



Door FR, Dent(s) and scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Acceptable



Wing RR, Bad repair, Check



Alloy rim RR, Scratch(es), Acceptable



Roof, Dent(s), Paintless dent repair

