



## SKODA Octavia

### Octavia Combi 1.2 TSI (Green tec)

VIN NO TMBJA7NE9G0256226

Registration Number E9G0256226



#### MOT Date

2025-10-01

#### Last Service



#### Number of Owners

2

#### Last Service Mileage



#### Number of Keys

2

#### First Registration Date

2016-07-11

#### Odometer Reading

104782 km

#### Country First Registered

Germany

### Inspection Report Summary

Customer	BCA Online	Report Number	P20251014110535
Inspection Date / Place	2025-10-14 / SULOJA Brackel	Cosmetic Grade	5

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	110
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available	-	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	Trip Computer	Airbag Status	Anti-lock braking
Bluetooth telephone interface	Front fog lamps	Heated wing mirrors	Remote central locking
Split folding rear seats	CD - multichanger	Leather steering wheel	Rain sensitive windscreen wipers
Tow ball	USB Socket	Alloys wheels	Auxiliary Socket
Cruise control	Front parking sensors	Remote adjusting wing mirrors	Roof rails
Stability control	Electric tailgate	Radio	Rear parking sensors

Equipment Details

Tow Ball Type	Static	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	17	Seat Heating	No


Wheels & Tyres

Right Rear Tyre Depth	5	Left Rear Tyre Depth	5
Right Front Tyre Depth	5	Left Front Tyre Depth	5




Cosmetic Damage

23 Schäden




3 Schäden



Component		Damage	Comments
1	Door / Back Right	Paint / Scratch / Scuff	
2	Roof	Paint / Scratch / Scuff	
3	Door / Back Left	Paint / Scratch / Scuff	
4	Side Panel / Back Right	Paint / Scratch / Scuff	
5	Bumper / Back	Paint / Scratch / Scuff	
6	Tailgate	Paint / Scratch / Scuff	
7	Side Panel / Back Left	Paint / Scratch / Scuff	
8	Fender / Front Right	Paint / Scratch / Scuff	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Roof	Paint / Scratch / Scuff	
11	Bumper / Back	Paint / Scratch / Scuff	
12	Rocker Panel / Center Right	Paint / Scratch / Scuff	

13	Door / Front Right	Paint / Scratch / Scuff
14	Door / Front Left	Paint / Scratch / Scuff
15	Side Panel / Back Right	Paint / Scratch / Scuff
16	Hood	Paint / Poor Previous Repair
17	Bumper / Front	Bodywork / Dent / Dent
18	Mirror / Front Right	Paint / Scratch / Scuff
19	Door / Back Left	Paint / Scratch / Scuff
20	Panel Filling / Front Right	Interior / Scratched
21	Panel Filling / Back Left	Interior / Scratched
22	Bumper / Front	Paint / Scratch / Scuff
23	Interior door handle Back right	Interior / Scratched
24	Side Panel / Back Left	Bodywork / Dent / Dent
25	Windshield / Front	Glass Break
26	Windshield / Front	Glass Break / Scratch / Scratch



1. Door / Back Right  
Paint / Scratch / Scuff -



2. Roof  
Paint / Scratch / Scuff -



3. Door / Back Left  
Paint / Scratch / Scuff -



4. Side Panel / Back Right  
Paint / Scratch / Scuff -



5. Bumper / Back  
Paint / Scratch / Scuff -




6. Tailgate  
Paint / Scratch / Scuff -





7. Side Panel / Back Left  
Paint / Scratch / Scuff -



8. Fender / Front Right  
Paint / Scratch / Scuff -



9. Bumper / Back  
Paint / Scratch / Scuff -



10. Roof  
Paint / Scratch / Scuff -




11. Bumper / Back  
Paint / Scratch / Scuff -



12. Rocker Panel / Center Right  
Paint / Scratch / Scuff -






13. Door / Front Right  
Paint / Scratch / Scuff -



14. Door / Front Left  
Paint / Scratch / Scuff -



15. Side Panel / Back Right  
Paint / Scratch / Scuff -



16. Hood  
Paint / Poor Previous Repair -




17. Bumper / Front  
Bodywork / Dent / Dent -



18. Mirror / Front Right  
Paint / Scratch / Scuff -






19. Door / Back Left  
Paint / Scratch / Scuff -



20. Panel Filling / Front Right  
Interior / Scratched -



21. Panel Filling / Back Left  
Interior / Scratched -



22. Bumper / Front  
Paint / Scratch / Scuff -



23. Interior door handle Back right  
Interior / Scratched -



24. Side Panel / Back Left  
Bodywork / Dent / Dent -





25. Windshield / Front  
Glass Break -



26. Windshield / Front  
Glass Break / Scratch / Scratch -

## Mechanical Condition

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

### Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

### Gearbox

Gear Box	✓
----------	---

### Equipments Test

Electric Windows	✓	Audio Equipment	✓
AC / Heating System	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel

Steering | Noise / Anomaly

Engine

Engine Noise The Gears Scratch / Skip / Abnormal Operation

Fume Quantity Power Loss

Brake

Brake System Anomaly

Clutch

Clutch Functioning

General

Test Driven Status

- No troubles detected, good condition or correct tests, according to vehicle age and mileage
- Damages or malfunction detected that requires repairs by the buyer
- Not applicable
- Not tested

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description. [User Guide](#)