



Skoda Kodiaq: J961GZ

Vinnumber:	TMBJB9NS6L8067690	Versionname:	Kodiaq 1.5 TSI ACT 110kW Sportline Business DSG
First Registrationdate:	7/08/2020	Fiscalpower:	
Expertise Mileage:	89135	Power Kw:	110
Bodytype:		Body colour	Quartz Grey
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Type of rims (mounted)	Aluminium
Fueltype:	Petrol	Parking lot	543
Number of seats	7		
Type of rims (mounted)	Aluminium		
Maintenance needed	Yes		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Lining Alcantara
Windows electric F		Sun Roof electric
Radio multimedia		Panoramic roof
		Central consol F
		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Hook

Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 45 / 20 / 100 / V / Aluminium	7,7 mm	Continental	Summer
	Right	235 / 45 / 20 / 100 / V / Aluminium	7,9 mm	Continental	Summer
Rear	Left	235 / 45 / 20 / 100 / V / Aluminium	7,0 mm	Continental	Summer
	Right	235 / 45 / 20 / 100 / V / Aluminium	5,9 mm	Continental	Summer

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service, Maintenance, Execute



User's manual, Missing, Replace

No pictures to display

Door FL, Bad repair, Repair and paint (complete)



Door RL, Bad repair, Repair and paint (complete)



Wing RL, Bad repair, Repair and paint (complete)



 [Damage Picture - 2](#)

Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Tow bar (fixed), Deformed / Strained, Replace



Bumper R, Scratch(es), Repair and paint (complete)

