



Skoda Kodiaq: K061XF

Vinnnummer:	TMBJB9NS7M8513377	Versionname:	Kodiaq 1.5 TSI ACT 110kW Sportline Business DSG
First Registrationdate:	26/03/2021	Fiscalpower:	
Expertise Mileage:	178558	Power Kw:	110
Bodytype:		Body colour:	Velvet Red metallic
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Petrol	Parking lot:	997
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Lining Alcantara
Windows electric F		Central consol F
Radio multimedia		Luggage cover
Keys removable towhook		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors
		Tow bar removable

Degree of wear

235/50/19/103 V				
Winter tyres:	Fr.L.	Michelin: 5,4 mm	Fr.R.	Michelin: 6,9 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5,3 mm
Tyre profile depth FL				5.4
Tyre profile depth FR				6.9
Tyre profile depth RL				5.0
Tyre profile depth RR				5.3
Tyre size FL				235/50 R 19 103 V
Tyre size FR				235/50 R 19 103 V
Tyre size RL				235/50 R 19 103 V
Tyre size RR				235/50 R 19 103 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				261
Tyre make FR				261
Tyre make RL				2480
Tyre make RR				2480

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Dashboard, Scratch(es), Smart repair



Door RL, Scratch(es), Repair and paint (complete)



Door trim RL, Scratch(es), Replace and paint



Bumper F, Scratch(es), Repair and paint (complete)



Bumper FM, Scratch(es), Repair and paint (complete)



Bumper moulding FL, Scratch(es), Replace



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Door RR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Bumper RM, Scratch(es), Repair and paint (complete)

