


Vehicle details

VIN	TMBJG7NE5 E0149248	Brand	SKODA	Maintenance date	-
Licence Plate	5T-GZ-58	Model	OCTAVIA COMBI 1.6 TDI Greentech Ambition 5d	Maintenance mileage	-
Registration date	04/02/2014	Year	2014	Exterior Color	White Solid
Odometer	207 710 km	Engine size	1598	interior Color	Grey
Fuel	Diesel	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	19/05/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Audio System	✓

Removable element


Load cover	✓
------------	---

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit



Exterior

9		Part Position Damages Severity Repair mode	Wing Front left Scratched Length (cm) > 10 Repair	10		Part Position Damages Severity Repair mode	Exterior door mirror shell Right Improper repair - Repair
11		Part Position Damages Severity Repair mode	Bumper Front Scratched Length (cm) > 10 Repair	12		Part Position Damages Severity Repair mode	Bonnet - Dent & Chips Diameter (mm) > 20 Repair
13		Part Position Damages Severity Repair mode	Roofrail Left Perforated - Replace	14		Part Position Damages Severity Repair mode	Roofrail Right Perforated - Replace
15		Part Position Damages Severity Repair mode	Roof - Dent & Chips Diameter (mm) > 20 Repair				

Interior damage

1		Part Position Damages Severity Repair mode	Interior tailgate lining Down Scratched - Smart Repair				
2		Part Position Damages Severity Repair mode	Panel lining wood/fabric Back right Perforated - Replace	3		Part Position Damages Severity Repair mode	Panel lining wood/fabric Back left Perforated - Replace
4		Part Position Damages Severity Repair mode	Interior roof lining Front Pierced - Smart Repair	5		Part Position Damages Severity Repair mode	Dashboard trim Centre Pierced - Replace

6



Part

Dashboard

Position

Front right

Damages

Pierced

Severity

-

Repair mode

Smart Repair

●

●

7



Part

Dashboard trim

Position

Front right

Damages

Pierced

Severity

-

Repair mode

Replace

●

●

8



Part

Seat complete

Position

Front left

Damages

Missing

Severity

-

Repair mode

Replace

●