


Vehicle details

VIN	TMBJG7NE5 K0149035	Brand	SKODA	Maintenance date	-
Licence Plate	W17993J	Model	OCTAVIA Combi 1,6 TDI SCR Ambition DSG 85KW	Maintenance mileage	-
Registration date	21/03/2019	Year	1000	Exterior Color	White Solid
Odometer	175 265 km	Engine size	1598	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/03/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	02/05/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element




Technical Document

User manual	✓
Log books	✓
Remote key	✓

Tyres

Winter kit

Pirelli 205/55/16 H Winter 4.9 mm



Pirelli 205/55/16 H Winter 5.0 mm



Pirelli 205/55/16 H Winter 6.6 mm

Pirelli 205/55/16 H Winter 6.5 mm

Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

2



Part	Bonnet
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

6



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	-
Repair mode	For info

7



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

9



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

11



Part	Roof
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

Interior damage

4



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

● ● ● ● ●

5



Part	Gear lever knob
Position	-
Damages	Scratched
Severity	-
Repair mode	Replace

● ●

10



Part	Fabric door lining
Position	Back right
Damages	Cut
Severity	-
Repair mode	Replace

● ●

8



Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

● ● ●

12



Part	Key
Position	-
Damages	Missing
Severity	-
Repair mode	Replace

●

Others

13



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint