



SKODA SUPERB COMBI: 1YLJ051

Vinnnumber:	TMBJG7NP8M7018208	Versionname:	1.6 CRTDI 88kW DSG7 Ambition
First Registrationdate:	29/09/2020	Fiscalpower:	
Expertise Mileage:	105791	Power Kw:	88
Bodytype:		Body colour	Grey
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Parking lot	3513
Fueltype:	Diesel		
Maintenance	OK		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		
Registration Certificate Home (BE)	No		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Seats electric F R	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	Headlighting LED	Type of Tow bar	No Tow bar
Type of GPS	GPS base		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Type of GPS storage	HD		

Limited Technical Inspection

Tyres

215/60/16/95 V			
Summer tyres:	Fr.L.	Continental: 5 mm	Fr.R. Continental: 5 mm
	Re.L.	Continental: 5 mm	Re.R. Continental: 5 mm
Tyre profile depth FL			5.0
Tyre profile depth FR			5.0
Tyre profile depth RL			5.0
Tyre profile depth RR			5.0
Tyre size FL			215/60 R 16 95 V
Tyre size FR			215/60 R 16 95 V
Tyre size RL			215/60 R 16 95 V
Tyre size RR			215/60 R 16 95 V
Tyre type FL			Summer
Tyre type FR			Summer
Tyre type RL			Summer
Tyre type RR			Summer
Tyre make FL			256
Tyre make FR			256
Tyre make RL			256
Tyre make RR			256

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2648,76
Engine insulation, Tear, Replace	57,51



Windscreen, Bad repair, Replace

1042,23



Bumper F, Deformed / Strained, Repair and paint (complete)

346,88



Fog lamp L, Deformed / Strained, Repair/replace (lump sum)

20,00



Outside rear-view mirror housing L, Crack, Replace

62,34



Mirror side repeater L, Broken, Replace

56,48



Wing RL, Dent(s) and scratch(es), Acceptable

0,00



Boot carpet, Chemical polution, Chemical cleaning

50,00



Tailgate / Boot, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Wing RR, Dent(s) and scratch(es), Repair and paint (complete)

504,77



Outer sill R, Dent(s) and scratch(es), Repair and paint (complete)	508,55
--	--------

