

**SKODA KAROQ: 1XSK815**

Vinnumber:	TMBJG7NU0L5034032	Versionname:	1.6 CRTDI 85KW Style
First Registrationdate:	4/05/2020	Fiscalpower:	
Expertise Mileage:	140151	Power Kw:	85
Bodytype:		Body colour:	Grey
Gearbox:	MAN 6 VIT	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	1314
Fueltype:	Diesel		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		

Options

Number of keys total	2	Seats electric F L	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection**Degree of wear**

	215/50/18/92 H			
Summer tyres:	Fr.L.	Bridgestone: 5 mm	Fr.R.	Bridgestone: 5 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/50 R 18 92 H
Tyre size FR				215/50 R 18 92 H
Tyre size RL				215/50 R 18 92 H
Tyre size RR				215/50 R 18 92 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				255
Tyre make FR				255
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	559,64
Alloy rim FR polished, Scratch(es), Acceptable	0,00



Wing FR, Dent(s) and scratch(es), Repair and paint (complete)	360,60
---	--------



Door RR, Dent(s) and scratch(es), Repair and paint (complete)	0,00
---	------



Wing FR, Dent(s), Acceptable	0,00
------------------------------	------



Alloy rim FR polished, Scratch(es), Repair and paint (complete)	199,04
---	--------

