

Vehicle details

VIN	TMBJG7NU4 L5023843	Brand	SKODA	Maintenance date	-
Licence Plate	W54582J	Model	Karoq 1,6 TDI Style Limited 85KW	Maintenance mileage	-
Registration date	16/01/2020	Year	1000	Exterior Color	Silver Metallic
Odometer	104 606 km	Engine size	1598	interior Color	Black
Fuel	Diesel	Body Type	SUV CrossOver	Next technical inspection	01/12/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	28/02/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element




Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Dunlop 215/60/16 H Winter 8.6 mm



Dunlop 215/60/16 H Winter 8.5 mm



Pirelli 215/60/16 H Winter 4.8 mm

Pirelli 215/60/16 H Winter 5.0 mm

Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	Diameter (mm) > 10
Repair mode	Replace

2



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

3



Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

5



Part	Wing
Position	Back left
Damages	Dent & Chips
Severity	-
Repair mode	Repair

6



Part	Door moulding
Position	Front left
Damages	Scratched
Severity	-
Repair mode	Replace

8



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Replace

9



Part	Door
Position	Back right
Damages	Scratched
Severity	-
Repair mode	For info

10



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info

11



Part	Roof
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

Interior damage

7



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others

12



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint



13		Part	Paint preparation
		Position	-
		Damages	-
		Severity	-
		Repair mode	Paintworks