



Skoda Octavia (UKL): 2BMB940

Vinnumber:	TMBJG7NX5NY057141	Versionname:	Octavia Combi Clever 2.0TDi 115pk/cv 5p DSG7
First Registrationdate:	11/01/2022	Fiscalpower:	
Expertise Mileage:	175294	Power Kw:	85
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		


Tyres

205/60/16/92 V				
Summer tyres:	Fr.L.	Kumho: 2 mm	Fr.R.	Kumho: 2 mm
	Re.L.	Kumho: 3 mm	Re.R.	Kumho: 3 mm
Tyre profile depth FL				2.0
Tyre profile depth FR				2.0
Tyre profile depth RL				3.0
Tyre profile depth RR				3.0
Tyre size FL				205/60 R 16 92 V
Tyre size FR				205/60 R 16 92 V
Tyre size RL				205/60 R 16 92 V
Tyre size RR				205/60 R 16 92 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				2482
Tyre make FR				2482
Tyre make RL				2482
Tyre make RR				2482

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bonnet, Hail damage, Repair and paint (complete)





Windscreen, Stone chip(s), Windscreen repair



Bumper F, Dent(s) and scratch(es), Repair and paint (complete)



Bumper moulding F, Scratch(es), Replace



Roof pillar L, Hail damage, Repair and paint (complete)



Alloy rim FL, Scratch(es), Acceptable



Alloy rim RL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Roof pillar R, Hail damage, Paintless dent repair



Wing RR, Dent(s) and scratch(es), Acceptable



Alloy rim RR, Scratch(es), Repair and paint (complete)



Roof, Hail damage, Repair and paint (complete)

