



Skoda Octavia: G027TG

Vinnnummer:	TMBJG9NE1K0119509	Versionname:	Octavia 1.6 TDI Greent.85kW Sport Bus.combi DSG (outgoing)
First Registrationdate:	2/12/2019	Fiscalpower:	85
Expertise Mileage:	118603	Power Kw:	85
Bodytype:		Body colour:	Black Magic Pearl effect
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Type of rims (mounted):	Aluminium
Fueltype:	Diesel	Parking lot:	379
Number of seats:	5		
Type of rims (mounted):	Aluminium		
Maintenance needed:	No		

Options

Number of keys total	2	Telephone equipment
Number keys remote	2	Central consol F
GPS		Luggage cover
GPS storage		Headlights Xenon/LED/Laser
Autom climate control		Rear parking sensors
Windows electric F		Hook
Radio multimedia		

Degree of wear

225/40/18/92 V				
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4,5 mm
Tyre profile depth FL				5.0
Tyre profile depth FR				5.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.5
Tyre size FL				225/40 R 18 92 V
Tyre size FR				225/40 R 18 92 V
Tyre size RL				225/40 R 18 92 V
Tyre size RR				225/40 R 18 92 V
Tyre type FL				Winter
Tyre type FR				Winter
Tyre type RL				Winter
Tyre type RR				Winter
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Number of charging cables (normal)	0
Number of charging cables (rapid charge)	0

Service book, Missing, Replace

No pictures to display

Wing FL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)



Bonnet, Chemical polution, Polish



Windscreen, Stone chip(s), Windscreen repair



Door FR, Dent(s) and scratch(es), Repair and paint (complete)



Wing RR, Scratch(es), Polish



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Outer door handle FR, Scratch(es), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)

