


Vehicle details

VIN	TMBJJ7NE1 L0126709	Brand	SKODA	Maintenance date	-
Licence Plate	W49066J	Model	OCTAVIA Combi 2,0 TDI Style Limited DSG 110KW	Maintenance mileage	-
Registration date	05/02/2020	Year	1000	Exterior Color	Black Pearl
Odometer	177 951 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/02/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	14/04/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element



Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Michelin 205/55/16 H Winter 6.5 mm		Michelin 205/55/16 H Winter 6.6 mm	
Michelin 205/55/16 H Winter 4.9 mm		Michelin 205/55/16 H Winter 5.0 mm	

Exterior

1		Part	Windscreen	2		Part	Bonnet
		Position	-			Position	-
		Damages	Stone impact			Damages	Dent & Chips
		Severity	-			Severity	-
		Repair mode	For info			Repair mode	Repair

3



Part

Bumper

Position

Front

Damages

Scratched

Severity

-

Repair mode

Repair

4



Part

Door

Position

Front left

Damages

Scratched

Severity

-

Repair mode

For info

5



Part

Wing

Position

Back left

Damages

Dent & Chips

Severity

-

Repair mode

Repair

9



Part

Tailgate / Boot door

Position

-

Damages

Dent & Chips

Severity

-

Repair mode

Repair

10



Part

Bumper

Position

Back

Damages

Scratched

Severity

-

Repair mode

Repair

11



Part

Wing

Position

Back right

Damages

Dent & Chips

Severity

-

Repair mode

Repair

12



Part

Door

Position

Front right

Damages

Scratched

Severity

-

Repair mode

For info

13



Part

Roof

Position

-

Damages

Stone impact

Severity

-

Repair mode

For info

Interior damage

6



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

7



Part	Floor mat
Position	Front left
Damages	Cut
Severity	-
Repair mode	Replace

8



Part	Carpet
Position	-
Damages	Cut
Severity	-
Repair mode	Replace

Others

14



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks



15		Part	Paint preparation
		Position	-
		Damages	-
		Severity	-
		Repair mode	Plastic paint