

Vehicle details

VIN	TMBJJ7NE5 L0126812	Brand	SKODA	Maintenance date	-
Licence Plate	W96967J	Model	OCTAVIA Combi 2,0 TDI Style Limited DSG 110KW	Maintenance mileage	-
Registration date	30/01/2020	Year	1000	Exterior Color	White Solid
Odometer	113 470 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/01/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	13/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element




Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Pirelli 205/55/16 H Winter 7.0 mm



Pirelli 205/55/16 H Winter 7.6 mm



Pirelli 205/55/16 H Winter 8.2 mm

Pirelli 205/55/16 H Winter 8.0 mm

Exterior

1		Part	Bumper	2		Part	Door sill
		Position	Front			Position	Back left
		Damages	Scratched			Damages	Dented
		Severity	-			Severity	-
		Repair mode	Repair			Repair mode	Repair

3



Part

Bumper

Position

Back

Damages

Scratched

Severity

-

Repair mode

Repair

●

●

●

●

4



Part

Tailgate / Boot door

Position

-

Damages

Scratched

Severity

-

Repair mode

Repair

●

●

●

6



Part

Wing

Position

Front right

Damages

Dent & Chips

Severity

-

Repair mode

Repair

●

●

Interior damage

5



●●

Part	Interior tailgate lining
Position	Down
Damages	Scratched
Severity	-
Repair mode	Replace

7



●●●●

Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

8



●

Part	Floor mat
Position	-
Damages	Cut
Severity	-
Repair mode	Replace

9



●●

Part	Carpet
Position	-
Damages	Cut
Severity	-
Repair mode	Replace

Others

10

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

11

Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint