

Vehicle details

VIN	TMBJJ7NE9 K0222652	Brand	SKODA	Maintenance date	-
Licence Plate	W31065C	Model	OCTAVIA Combi 2,0 TDI Style Limited DSG 110KW	Maintenance mileage	-
Registration date	26/06/2019	Year	1000	Exterior Color	Silver Metallic
Odometer	86 462 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/06/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	04/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element




Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Goodyear 205/55/16 H Winter 6.2 mm



Goodyear 205/55/16 H Winter 6.3 mm



Goodyear 205/55/16 H Winter 7.2 mm

Goodyear 205/55/16 H Winter 7.2 mm

Exterior

1



Part	Windscreen
Position	-
Damages	Stone impact
Severity	-
Repair mode	For info

2



Part	Bonnet
Position	-
Damages	Dent & Chips
Severity	-
Repair mode	Repair

3



● ● ●

Part	Bumper
Position	Front
Damages	Scratched
Severity	-
Repair mode	Repair

4



Part	Door
Position	Front left
Damages	Scratched
Severity	-
Repair mode	For info

5



● ●

Part	Door lock trim
Position	Front left
Damages	Missing
Severity	-
Repair mode	Replace

6



Part	Tailgate / Boot door
Position	-
Damages	Dented
Severity	-
Repair mode	For info

7



● ● ●

Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	Repair

8



Part	Door
Position	Front right
Damages	Scratched
Severity	-
Repair mode	For info


9



● ●

Part	Roof
Position	-
Damages	Dented
Severity	-
Repair mode	Repair


10



Part	Roof
Position	-
Damages	Dented
Severity	-
Repair mode	Repair

Interior damage

10



Part	Interior cleaning
Position	-
Damages	Not carried out
Severity	-
Repair mode	Lumpsum

Others

11



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks

12



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint