DEKRA

DEKRA Automotive Solutions

Appraisal Report

Vehicle details

VIN	TMBJJ7NEX L0185970	Brand	SKODA	Maintenance date	-
Licence Plate	DO784GC	Model	OCTAVIA Combi 2,0 TDI Ambition Limited DSG 110KW	Maintenance mileage	-
Registration date	04/08/2020	Year	1000	Exterior Color	Silver Metallic
Odometer	186 824 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/08/2025
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	19/03/2025	Inspection loc.	Hödlmayr Logistics GmbH

Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓
Heating seats	✓

Removable element

Technical Document

User manual	✓
Log books	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Dunlop 205/55/16 H Winter 8.1 mm

Dunlop 205/55/16 H Winter 8.1 mm



Dunlop 205/55/16 H Winter 8.8 mm

Dunlop 205/55/16 H Winter 8.7 mm

Exterior

1		Part	Windscreen
		Position	-
		Damages	Stone impact
		Severity	-
		Repair mode	For info
2		Part	Bonnet
		Position	-
		Damages	Dented
		Severity	-
		Repair mode	Repair
3		Part	Bumper
		Position	Front
		Damages	Scratched
		Severity	-
		Repair mode	Repair
4		Part	Door
		Position	Front left
		Damages	Scratched
		Severity	-
		Repair mode	For info
5		Part	Wing
		Position	Back left
		Damages	Dent & Chips
		Severity	-
		Repair mode	Repair
6		Part	Door sill
		Position	Back left
		Damages	Dent & Chips
		Severity	-
		Repair mode	Repair
10		Part	Tailgate / Boot door
		Position	-
		Damages	Dented
		Severity	-
		Repair mode	Repair
11		Part	Bumper
		Position	Back
		Damages	Scratched
		Severity	-
		Repair mode	Repair
12		Part	Alloy wheel 16"
		Position	Back right
		Damages	Scratched
		Severity	Length (cm) > 10
		Repair mode	Smart Repair
13		Part	Wing
		Position	Back right
		Damages	Dent & Chips
		Severity	-
		Repair mode	Repair
14		Part	Door
		Position	Back right
		Damages	Dent & Chips
		Severity	-
		Repair mode	Repair
15		Part	Door
		Position	Front right
		Damages	Dented
		Severity	-
		Repair mode	Repair
16		Part	Roof
		Position	-
		Damages	Stone impact
		Severity	-
		Repair mode	For info

Interior damage

7		Part	Interior cleaning
		Position	-
		Damages	Not carried out
		Severity	-
		Repair mode	Lumpsum

8		Part	Floor mat	9		Part	Gear lever knob
		Position	Front left			Position	-
		Damages	Cut			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Replace

Others

17		Part	Paint preparation	18		Part	Paint preparation
		Position	-			Position	-
		Damages	-			Damages	-
		Severity	-			Severity	-
		Repair mode	Paintworks			Repair mode	Plastic paint