

INSPECTION REPORT

End Of Contract

GENERAL INFO

File	286483
License plate	1XUS772
Vehicle identification number	TMBJJ7NSS5L8054520
Dossier	2020034099
Make	Skoda Kod.2.0CRTDI 110kW Style
Mileage	123531.00
First registration	29/05/2020
	24/06/2025

CHECK POINTS

Description	Number	Present	Remark
Original license plate		Y	
Registration Part 2		N	
Keys	1	Y	
Spare wheel		N	
Towbar (+keys)		N	
Certificate of conformity		Y	
Registration certificate		Y	
Repair kit		Y	
RunOnFlat		N	
Charging cable		N	
Charge back wrong tyres		N	





DAMAGES

Damages	Type	Acceptable
222	Side View Mirror Right // Painting	Y
223	Side View Mirror Right // Replace Not Painted	Y
76	Side View Mirror Left / Shell / Replace Painted	Y
84	Door Front Left // Repair & Painting	Y
103	Door Rear Left // Painting	N
116	Wing Rear Left // Polish	Y
156	Rear Bonnet // Polish	Y
883	Key Price Range 2 //	N

Damage Pictures



Rear Bonnet // Polish-scratch



Wing Rear Left // Polish-scratch




Door Rear Left // Painting-scratch



Door Front Left // Repair & Painting-scratch + dent



Side View Mirror Left / Shell / Replace Painted-scratch + dent



Side View Mirror Right // Painting-scratch



Side View Mirror Right // Replace Not Painted-scratch