

Vehicle details

VIN	TMBJJ7NX1 MY030924	Brand	SKODA	Maintenance date	-
Licence Plate	W31615K	Model	OCTAVIA Combi 2,0 TDI Premium DSG 110KW	Maintenance mileage	-
Registration date	05/10/2020	Year	1000	Exterior Color	Black Pearl
Odometer	93 978 km	Engine size	1968	interior Color	Black
Fuel	Diesel	Body Type	Estate	Next technical inspection	01/10/2025
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details


Inspection date	04/03/2025	Inspection loc.	Hödlmayr Logistics GmbH
-----------------	------------	-----------------	-------------------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
Rain and light sensor	✓
GPS system	✓
Xenon projectors	✓
Anti-fog lights	✓
Front radars	✓
Alloy wheel rims	✓
Reversing radars	✓
Reversing camera	✓
Automatic Gearbox	✓

Removable element



Technical Document

Service manual holder	✓
User manual	✓
Spare key	✓
Remote key	✓

Tyres

Winter kit

Dunlop 205/60/16 H Winter 5.4 mm		Dunlop 205/60/16 H Winter 5.2 mm	
Dunlop 205/60/16 H Winter 6.0 mm		Dunlop 205/60/16 H Winter 5.8 mm	

Exterior

1		Part	Headlight	2		Part	Bumper
		Position	Front right			Position	Front
		Damages	Broken			Damages	Scratched
		Severity	-			Severity	-
		Repair mode	Replace			Repair mode	Repair

3



Part	Bumper
Position	Back
Damages	Scratched
Severity	-
Repair mode	For info

4



Part	Tailgate / Boot door
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

5



Part	Bonnet
Position	-
Damages	Scratched
Severity	-
Repair mode	Repair

Others

6



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Plastic paint

7



Part	Paint preparation
Position	-
Damages	-
Severity	-
Repair mode	Paintworks