



SKODA OCTAVIA COMBI: 1YLZ920

Vinnnumber:	TMBJJ7NX1MY043107	Versionname:	2.0 CRTDI 110kW DSG7 Ambition
First Registrationdate:	5/10/2020	Fiscalpower:	
Expertise Mileage:	107767	Power Kw:	110
Bodytype:		Parking lot	1510
Gearbox:	Automatic	Type of rims (mounted)	Aluminium
Transmission:		Body colour	Blue
Fueltype:	Diesel		
Certificate of Conformity	Yes		
Type of rims (mounted)	Aluminium		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Radio multimedia		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Sun Roof electric	
Type of GPS	GPS big screen color	Front parking sensors	
Cruise Control		Panoramic roof	
Type of climate control	Autom climate control	Type of Tow bar	No Tow bar
Number of keys total	2		
Type of headlighting	Headlighting LED		
Type of Lining	Lining semi-artificial leather		

Limited Technical Inspection

Tyres

Tyre size RL	205/55 R 17 92 H
Tyre type FL	Summer
Tyre type RL	Winter
Tyre profile depth FR	5.0
Tyre profile depth RR	5.0
Tyre make FR	2480
Tyre size FR	205/55 R 17 92 H
Tyre make RR	2480
Tyre size RR	205/55 R 17 92 H

205/55/17/92 H

Summer tyres:	Fr.L.	Vredestein: 5 mm	Fr.R.	Vredestein: 5 mm
	Re.L.	Vredestein: 5 mm	Re.R.	Vredestein: 5 mm

Tyre profile depth FL	5.0
Tyre make FL	2480
Tyre size FL	205/55 R 17 92 H
Tyre type FR	Winter
Tyre profile depth RL	5.0
Tyre type RR	Winter
Tyre make RL	2480

Assistance equipment

Number of charging cables (normal)	0	Jack	Yes
Number of charging cables (rapid charge)	0		
Spare wheel	Yes		

Total cost ex VAT	543,70
Seat cover FL, Damaged, Acceptable	0,00



Door FL, Dent(s), Paintless dent repair 93,06



Rear window, Scratch(es), Replace 0,00



Tailgate / Boot, Scratch(es), Spot repair 144,58



Alloy rim FR, Scratch(es), Repair and paint (complete) 129,66



Tyre FR, Tear, Replace 176,40



Wing RR, Dent(s), Acceptable 0,00

