



Skoda Octavia (UKL): 1YHZ435

Vinnumber:	TMBJJ7NX4MY017164	Versionname:	Octavia Combi Ambition 2.0TDi 150pk/cv 5p DSG7
First Registrationdate:	8/09/2020	Fiscalpower:	
Expertise Mileage:	199083	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	3	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	205/60/16/91 H			
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 4 mm	Re.R.	Goodyear: 4 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/60 R 16 91 H
Tyre size FR				205/60 R 16 91 H
Tyre size RL				205/60 R 16 91 H
Tyre size RR				205/60 R 16 91 H
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				256
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

GPS, Not functioning (well), Check



Bumper F, Scratch(es), Acceptable



Bonnet, Dent(s), Acceptable



Windscreen, Stone chip(s), Windscreen repair



Door FL, Scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Tailgate / Boot, Scratch(es), Acceptable




Wing RR, Dent(s) and scratch(es), Repair and paint (complete)



Alloy rim RR, Scratch(es), Acceptable



Alloy rim FR, Scratch(es), Repair and paint (complete)



Door FR, Scratch(es), Spot repair



Roof, Dent(s), Paintless dent repair

