



SKODA OCTAVIA COMBI: 2AAC881				
Vinnnumber:	TMBJJ7NX7MY102838	Versionname:	2.0 CRTDI 110kW DSG7 Style	
First Registrationdate:	28/01/2021	Fiscalpower:		
Expertise Mileage:	82207	Power Kw:	110	
Bodytype:		Body colour	Black	
Gearbox:	Automatic	Type of rims (mounted)	Aluminium	
Transmission:		Parking lot	1225	
Fueltype:	Diesel			
Type of rims (mounted)	Aluminium			
Certificate of Conformity	Yes			
Category	Passenger Car			
Registration Certificate Car (BE)	Yes			
Options				
Number of keys total	3	Luggage cover		
Cruise Control		Front parking sensors		
Steering wheel multifunctional		Rear parking sensors		
Seats F heated		Type of Tow bar	No Tow bar	
Radio multimedia				
Type of headlighting	Headlighting LED			
Type of GPS	GPS big screen color			
Type of Lining	Lining fabrics			
Type of climate control	Autom climate control			
Limited Technical Inspection				
Tyres				
Summer tyres:	205/55/17/92 H			
	Fr.L.	Hankook: 5 mm	Fr.R.	Hankook: 5 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm
Tyre profile depth FL			5.0	
Tyre profile depth FR			5.0	
Tyre profile depth RL			5.0	
Tyre profile depth RR			5.0	
Tyre size FL			205/55 R 17 92 H	
Tyre size FR			205/55 R 17 92 H	
Tyre size RL			205/55 R 17 92 H	
Tyre size RR			205/55 R 17 92 H	
Tyre type FL			Summer	
Tyre type FR			Summer	
Tyre type RL			Summer	
Tyre type RR			Summer	
Tyre make FL			260	
Tyre make FR			260	
Tyre make RL			256	
Tyre make RR			256	
Assistance equipment				
Spare wheel	Yes	Jack	Yes	
Number of charging cables (normal)	0			
Number of charging cables (rapid charge)	0			
Total cost ex VAT			420,65	
Bumper moulding F, Chemical polution, Acceptable			0,00	




Bumper F, Scratch(es), Acceptable

0,00



Bonnet, Scratch(es), Acceptable

0,00



Wing RL, Dent(s) and scratch(es), Repair and paint (complete)

420,65



Alloy rim FL, Scratch(es), Acceptable

0,00



Bumper R, Scratch(es), Acceptable

0,00



Alloy rim FR, Scratch(es), Acceptable

0,00



Roof, Dent(s), Acceptable

0,00

