



SKODA Kodiaq

Kodiaq 2.0 TDI DSG

VIN NO TMBJJ7PS2ST043127
Registration Number S2ST043127



MOT Date

2028-01-01

Last Service



Number of Owners

1

Last Service Mileage



Number of Keys

2

First Registration Date

2025-01-14

Odometer Reading

53 km

Country First Registered

Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20250926143202
Inspection Date / Place	2025-09-26 / BCA Neuss	Cosmetic Grade	2

Vehicle Summary


Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Diesel	Gearbox Type	Automatic
Colour	White	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	Schwarz	Seat Covering	Cloth/Synthetic Leather
Charging Cables		WLTP CO2 Emissions	

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tinted Glass	360°camera	Alloys wheels	Anti-lock braking
Cruise control	Digitaldashboard	Heated wing mirrors	Remote central locking
Roof rails	Seatventilation	Electrically adjustable seats	Electrictailgate
LED Headlamps	Rear parking sensors	USB Socket	Airbag Status
Ambientlighting	Bluetooth telephone interface	Diesel particulate filter	Front parking sensors
Remote adjusting wing mirrors	Reversing Camera	Satellite navigation	Stability control
Electrically folding wing mirrors	Leather steering wheel	Radio	

Equipment Details


Air Conditioning	Three Zone Climate Control	Alloy Wheel Size	18
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front and Rear

Wheels & Tyres


Right Front Tyre Depth	6	Left Front Tyre Depth	6
Right Rear Tyre Depth	7	Left Rear Tyre Depth	7
Extra Wheel - 1 Tyre Depth	8	Extra Wheel - 2 Tyre Depth	8
Extra Wheel - 3 Tyre Depth	8	Extra Wheel - 4 Tyre Depth	8

Cosmetic Damage

1 Schäden



0 Schäden



Component		Damage	Comments
1	Door / Front Left	Paint / Poor Previous Repair	



1. Door / Front Left
Paint / Poor Previous Repair -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	✓	Display Defect	✓
Tire Pressure Monitoring System	✓		

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	AC / Heating System	✓
Main & Spare Keys Functioning	✓	Parking Sensors / Cameras Functioning	✓

Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly		✓	
General			
Test Driven Status		✓	
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
= <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)