



# SKODA Fabia

## Fabia Combi 1.2 TSI

VIN NO TMBJN6NJXFZ078090  
Registration Number JXFZ078090



MOT Date	Number of Owners	Number of Keys	Odometer Reading
-	2	2	160393 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
-	-	2015-06-25	-

### Inspection Report Summary

Customer	BCA Online	Report Number	P20251001120310
Inspection Date / Place	2025-10-01 / ARS Altmann AG Riedstadt	Cosmetic Grade	4

### Vehicle Summary

Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Petrol	Road Worthy	Yes
Colour	Brown	Engine Size (cc)	1197
Engine Size	1.2	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	110
Gearbox Type	Manual		

### Vehicle History & Documents

Service Book Available	Missing	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







## Equipment

Tinted Glass	USB Socket	Anti-lock braking	Bluetooth telephone interface
Heated wing mirrors	Remote central locking	Stability control	Radio
Trip Computer	Airbag Status	Auxiliary Socket	Cruise control
Remote adjusting wing mirrors	Roof rails	Leather steering wheel	Rear parking sensors

## Equipment Details


Air Conditioning	Climate Control	Alloy Wheel Size	15
Seat Heating	Front		

## Wheels & Tyres

Right Front Tyre Depth	5	Left Front Tyre Depth	5
Right Rear Tyre Depth	5	Left Rear Tyre Depth	5

Cosmetic Damage

17 Schäden



0 Schäden




Component		Damage	Comments
1	Hood	Bodywork / Dent / Dent	
2	Bumper / Front	Paint / Scratch / Scuff	
3	Pillar / Back Left	Paint / Scratch / Scuff	
4	Fender / Back Left	Paint / Scratch / Scuff	
5	Fender / Back Left	Paint / Scratch / Scuff	
6	Tailgate	Paint / Scratch / Scuff	
7	Bumper / Back	Paint / Scratch / Scuff	
8	Rear Window / Back	Glass Break / Scratch / Scratch	
9	Bumper / Back	Paint / Scratch / Scuff	
10	Mirror / Front Right	Paint / Scratch / Scuff	
11	Door / Back Right	Bodywork / Dent / Dent	
12	Door / Back Right	Paint / Scratch / Scuff	

13	Door / Front Right	Bodywork / Dent / Dent
14	Door / Front Right	Paint / Scratch / Scuff
15	Fender / Front Right	Paint / Scratch / Scuff
16	Fender / Front Left	Bodywork / Dent / Dent
17	Fender / Front Left	Paint / Poor Previous Repair





1. Hood  
Bodywork / Dent / Dent -



2. Bumper / Front  
Paint / Scratch / Scuff -



3. Pillar / Back Left  
Paint / Scratch / Scuff -



4. Fender / Back Left  
Paint / Scratch / Scuff -



5. Fender / Back Left  
Paint / Scratch / Scuff -



6. Tailgate  
Paint / Scratch / Scuff -





7. Bumper / Back  
Paint / Scratch / Scuff -




8. Rear Window / Back  
Glass Break / Scratch / Scratch -



9. Bumper / Back  
Paint / Scratch / Scuff -



10. Mirror / Front Right  
Paint / Scratch / Scuff -




11. Door / Back Right  
Bodywork / Dent / Dent -




12. Door / Back Right  
Paint / Scratch / Scuff -





13. Door / Front Right  
Bodywork / Dent / Dent -



14. Door / Front Right  
Paint / Scratch / Scuff -



15. Fender / Front Right  
Paint / Scratch / Scuff -



16. Fender / Front Left  
Bodywork / Dent / Dent -



17. Fender / Front Left  
Paint / Poor Previous Repair -

## Mechanical Condition

### Engine

Engine Starts	✓	Engine Status / EML	✓
Engine Leak Visible	✓		

### Equipments Test

Central Locking	✓	Electric Windows	✓
Audio Equipment	✓	AC / Heating System	✓
Other Equipments	✓	Main & Spare Keys Functioning	✓
Parking Sensors / Cameras Functioning	✓		

### Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Service Light	✓
Tire Pressure Monitoring System	✓		





### Levels

Brakes Fluid	✓	Coolant Fluid	✓
--------------	---	---------------	---



Test Drive Inspection

Steering Wheel			
Steering   Noise / Anomaly		✓	
Engine			
Engine Noise	✓	Fume Quantity	✓
Power Loss	✓		
Brake			
Brake System Anomaly		✓	
Clutch			
Clutch Functioning		✓	
General			
Test Driven Status		✓	

-  **No troubles detected, good condition or correct tests, according to vehicle age and mileage**
-  **Damages or malfunction detected that requires repairs by the buyer**
-  **Not applicable**
-  **Not tested**

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)