




SKODA Superb Combi: 2AVL899

Vinnnumber:	TMBJN9NP1M7072595	Versionname:	Superb Combi 1.5 TSI ACT DSG7 Style
First Registrationdate:	4/08/2021	Fiscalpower:	110kW/150pk 5D/P Auto-7
Expertise Mileage:	71675	Power Kw:	110
Bodytype:	Automatic	Body colour:	Blue
Gearbox:	Front	Type of rims (mounted)	Aluminium
Transmission:	Petrol	Parking lot	c610
Fueltype:	Aluminium		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Bodywork:	Dirty		
Interior:	Dirty		

Options

Number of keys total	2	Radio	
Number keys remote	2	Lining leather	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Fog lights (front)	
Steering wheel multifunctional			
Seats F heated			
Alarm			
Navigation with screen			
Airco electronic			
Rims alloy			

Limited Technical Inspection

Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Transmission	OK

Tyres

		215/55/17/94 V			
Summer tyres:	Fr.L.	Pirelli: 3 mm	Fr.R.	Pirelli: 3 mm	
	Re.L.	Pirelli: 3 mm	Re.R.	Michelin: 3 mm	
Tyre profile depth FL					3.0
Tyre profile depth FR					3.0
Tyre profile depth RL					3.0
Tyre profile depth RR					3.0
Tyre size FL					215/55 R 17 94 V
Tyre size FR					215/55 R 17 94 V
Tyre size RL					215/55 R 17 94 V
Tyre size RR					215/55 R 17 94 V
Tyre type FL					Summer
Tyre type FR					Summer
Tyre type RL					Summer
Tyre type RR					Summer
Tyre make FL					264
Tyre make FR					264
Tyre make RL					264
Tyre make RR					261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		


Interior, Smell, Ozone treatment



Bumper F, Scratch(es), Acceptable




Bonnet, Dent(s), Acceptable



Windscreen, Stone chip(s), Acceptable




Wing RL, Scratch(es), Polish






Door FL, Scratch(es), Acceptable



Door RL, Scratch(es), Acceptable



Wing RL, Bad repair, Spot repair



Luggage compartment cover, Damaged, Replace



Boot lid covering R, Scratch(es), Acceptable



Tailgate / Boot, Dent(s), Acceptable



Bumper R, Scratch(es), Polish




Alloy rim FR, Scratch(es), Acceptable



Wing FR, Scratch(es), Polish



Door FR, Dent(s), Acceptable



Outer door handle FR, Scratch(es), Acceptable



Door RR, Dent(s), Acceptable



Central pillar R, Dent(s) and scratch(es), Spot repair



Alloy rim RR, Scratch(es), Acceptable



Bodywork, No damage, Acceptable

