


Vehicle details

VIN	TMBJP6NXX LZ098345	Brand	SKODA	Maintenance date	-
Licence Plate	H8-62-RH	Model	FABIA COMBI 1.0 TSI 70kW Business Edition 5d	Maintenance mileage	-
Registration date	10/04/2020	Year	2020	Exterior Color	White Solid
Odometer	134 757 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	5		

Inspection Details

Inspection date	06/10/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Manual air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element


Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓

Tyres

Michelin 215/45/16 Summer 4.5 mm



Michelin 215/45/16 Summer 4.5 mm



Michelin 215/45/16 Summer 6.0 mm

Michelin 215/45/16 Summer 6.0 mm

Exterior

1



Part

Bonnet

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

●

●

4



Part

Wing

Position

Back left

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

11



Part

Wing

Position

Back right

Damages

Dented

Severity

Diameter (mm) > 20

Repair mode

Smart Repair

●

●

●

●

13



Part

Roof

Position

-

Damages

Chemical deposit

Severity

-

Repair mode

Lumpsum repair

●

●

●

2



Part

Bumper

Position

Front left

Damages

Perforated

Severity

-

Repair mode

Repair

●

●

●

●

10



Part

Bumper

Position

Back

Damages

Scratched

Severity

-

Repair mode

Repair

●

●

●

●

12



Part

Alloy wheel 16"

Position

Front right

Damages

Scratched

Severity

-

Repair mode

Lumpsum repair

●

●

●

14



Part

Windscreen

Position

-

Damages

Stone impact

Severity

-

Repair mode

For info

●

●

Interior damage

3		<table><tr><td>Part</td><td>Interior cleaning</td></tr><tr><td>Position</td><td>Front</td></tr><tr><td>Damages</td><td>Stained/dirty</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Cleaning</td></tr></table>	Part	Interior cleaning	Position	Front	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning	5		<table><tr><td>Part</td><td>Interior cleaning</td></tr><tr><td>Position</td><td>Back</td></tr><tr><td>Damages</td><td>Stained/dirty</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Cleaning</td></tr></table>	Part	Interior cleaning	Position	Back	Damages	Stained/dirty	Severity	-	Repair mode	Cleaning
Part	Interior cleaning																								
Position	Front																								
Damages	Stained/dirty																								
Severity	-																								
Repair mode	Cleaning																								
Part	Interior cleaning																								
Position	Back																								
Damages	Stained/dirty																								
Severity	-																								
Repair mode	Cleaning																								
6		<table><tr><td>Part</td><td>Interior tailgate lining</td></tr><tr><td>Position</td><td>Up</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Interior tailgate lining	Position	Up	Damages	Scratched	Severity	-	Repair mode	Replace	7		<table><tr><td>Part</td><td>Interior tailgate lining</td></tr><tr><td>Position</td><td>Left</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Interior tailgate lining	Position	Left	Damages	Scratched	Severity	-	Repair mode	Replace
Part	Interior tailgate lining																								
Position	Up																								
Damages	Scratched																								
Severity	-																								
Repair mode	Replace																								
Part	Interior tailgate lining																								
Position	Left																								
Damages	Scratched																								
Severity	-																								
Repair mode	Replace																								
8		<table><tr><td>Part</td><td>Interior tailgate lining</td></tr><tr><td>Position</td><td>Right</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Interior tailgate lining	Position	Right	Damages	Scratched	Severity	-	Repair mode	Replace	9		<table><tr><td>Part</td><td>Interior tailgate lining</td></tr><tr><td>Position</td><td>Down</td></tr><tr><td>Damages</td><td>Scratched</td></tr><tr><td>Severity</td><td>-</td></tr><tr><td>Repair mode</td><td>Replace</td></tr></table>	Part	Interior tailgate lining	Position	Down	Damages	Scratched	Severity	-	Repair mode	Replace
Part	Interior tailgate lining																								
Position	Right																								
Damages	Scratched																								
Severity	-																								
Repair mode	Replace																								
Part	Interior tailgate lining																								
Position	Down																								
Damages	Scratched																								
Severity	-																								
Repair mode	Replace																								