


Vehicle details

VIN	TMBJP9NE0 K0160214	Brand	SKODA	Maintenance date	-
Licence Plate	ZB-02-5F	Model	OCTAVIA COMBI 1.0 TSI Greentech Ambition Business	Maintenance mileage	-
Registration date	24/04/2019	Year	2019	Exterior Color	White Solid
Odometer	180 410 km	Engine size	999	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	09/09/2025	Inspection loc.	Dekra Ayvens
-----------------	------------	-----------------	--------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓

Removable element

Spare wheel kit	✓
Load cover	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Pirelli 205/55/16 Winter 8.5 mm	Pirelli 205/55/16 Winter 8.0 mm
Goodyear 205/55/16 Winter 8.5 mm	Goodyear 205/55/16 Winter 9.0 mm

Exterior

1



Part	Bonnet
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

2



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

● ●

3



Part	Wing
Position	Back right
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

4



Part	Alloy wheel 16"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

● ● ●

5



Part	Tailgate / Boot door
Position	Back
Damages	Rusty
Severity	Diameter (mm) > 4
Repair mode	Repair

● ● ●

6



Part	Wing
Position	Back left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

7



Part	Door
Position	Front left
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

● ●

8



Part	Bumper
Position	Back
Damages	Broken
Severity	Length (cm) > 10
Repair mode	Repair

● ●