



Skoda Fabia (UKL): 1YEH951

Vinnumber:	TMBJR6NJ1LZ120257	Versionname:	Fabia Combi Ambition 1.0TSi 110pk/cv 5p
First Registrationdate:	4/08/2020	Fiscalpower:	
Expertise Mileage:	157678	Power Kw:	81
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	MAN 6 VIT		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	No Tow bar
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

215/45/16/90 V				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Nexen: 3 mm	Re.R.	Nexen: 3 mm
Tyre profile depth FL	6.0			
Tyre profile depth FR	6.0			
Tyre profile depth RL	3.0			
Tyre profile depth RR	3.0			
Tyre size FL	215/45 R 16 90 V			
Tyre size FR	215/45 R 16 90 V			
Tyre size RL	215/45 R 16 86 H			
Tyre size RR	215/45 R 16 86 H			
Tyre type FL	Summer			
Tyre type FR	Summer			
Tyre type RL	Summer			
Tyre type RR	Summer			
Tyre make FL	259			
Tyre make FR	259			
Tyre make RL	1957072			
Tyre make RR	1957072			

Assistance equipment

Spare wheel	Yes	Jack	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Seat cover FL, Dirty, Cleaning



Backrest cover FL, Burned, Replace



Floor covering FL, Worn, Smart repair



Seat cover R, Stain, Cleaning




Seat cover FR, Dirty, Cleaning



Bumper F, Bad repair, Repair and paint (complete)



Windscreen, Scratch(es), Replace



Alloy rim RL, Scratch(es), Repair and paint (complete)



Wing RL, Dent(s), Paintless dent repair



Bumper R, Scratch(es), Acceptable



Wiper arm rear, Broken, Replace



Door FR, Dent(s), Paintless dent repair



Alloy rim FR, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing R, Scratch(es), Acceptable

