


SKODA OCTAVIA COMBI: 1YAW398

Vinnnumber:	TMBJR7NE4L0186136	Versionname:	1.5 TSI ACT GreenTec 110kW DSG7 Ambition
First Registrationdate:	2/07/2020	Fiscalpower:	
Expertise Mileage:	114421	Power Kw:	110
Bodytype:		Body colour:	Grey
Gearbox:	Automatic	Type of rims (mounted):	Aluminium
Transmission:		Parking lot:	2508
Fueltype:	Petrol		
Maintenance:	OK		
Type of rims (mounted):	Aluminium		
Certificate of Conformity:	Yes		
Category:	Passenger Car		
Registration Certificate Car (BE):	Yes		
Registration Certificate Home (BE):	No		

Options

Number of keys total:	2	Luggage cover:	
Cruise Control:		Front parking sensors:	
Steering wheel multifunctional:		Rear parking sensors:	
Seats F heated:		Type of Tow bar:	No Tow bar
Radio multimedia:			
Type of headlighting:	Headlighting Halogen		
Type of GPS:	GPS base		
Type of Lining:	Lining fabrics		
Type of climate control:	Autom climate control		
Type of GPS storage:	HD		

Limited Technical Inspection
Tyres

	205/55/16/91 V			
Summer tyres:	Fr.L.	Dunlop: 3,5 mm	Fr.R.	Dunlop: 3 mm
	Re.L.	Dunlop: 4 mm	Re.R.	Dunlop: 4 mm
Tyre profile depth FL				3.5
Tyre profile depth FR				3.0
Tyre profile depth RL				4.0
Tyre profile depth RR				4.0
Tyre size FL				205/55 R 16 91 V
Tyre size FR				205/55 R 16 91 V
Tyre size RL				205/55 R 16 91 V
Tyre size RR				205/55 R 16 91 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				257
Tyre make FR				257
Tyre make RL				257
Tyre make RR				257

Assistance equipment

Repair kit:	Yes	Compressor:	Yes
Number of charging cables (normal):	0		
Number of charging cables (rapid charge):	0		

Total cost ex VAT	552,74
Interior, Stain, Cleaning	170,61



Door panel RL, Scratch(es), Acceptable	0,00
--	------



Bumper F, Scratch(es), Repair and paint (complete)	289,07
--	--------



Alloy rim FL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim RL, Scratch(es), Acceptable	0,00
---------------------------------------	------



Door FL, Scratch(es), Acceptable	0,00
----------------------------------	------



Door RL, Dent(s), Acceptable	0,00
------------------------------	------



Rear window, Scratch(es), Replace	0,00
-----------------------------------	------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------



Alloy rim FR, Scratch(es), Acceptable	0,00
---------------------------------------	------



Alloy rim RR, Scratch(es), Acceptable	0,00
---------------------------------------	------





Step R, Dent(s), Acceptable	0,00
-----------------------------	------



Door FR, Dent(s), Paintless dent repair	93,06
---	-------

