



Skoda Karoq (UKL): 2CDD932

Vinnumber:	TMBJR7NU2N5041870	Versionname:	Karoq Style 1.5TSi 150pk/cv 5p DSG7
First Registrationdate:	13/06/2022	Fiscalpower:	
Expertise Mileage:	53450	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar fixed
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/55/17/94 V			
Summer tyres:	Fr.L.	Goodyear: 4 mm	Fr.R.	Goodyear: 4 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm
Tyre profile depth FL				4.0
Tyre profile depth FR				4.0
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Bumper F, Scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Repair and paint (complete)



Wing RL, Scratch(es), Repair and paint (complete)



Door FL, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Step R, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Door FR, Dent(s), Acceptable



Roof pillar R, Dent(s), Acceptable



Wing trim RR, Dent(s), Replace



Alloy rim FR, Scratch(es), Repair and paint (complete)

