


Vehicle details

VIN	TMBJR7NU9 M5023879	Brand	SKODA	Maintenance date	-
Licence Plate	K2-64-VP	Model	Karoq 1.5 TSI ACT Greentech DSG Sportline Buss 5d	Maintenance mileage	-
Registration date	18/03/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	74 767 km	Engine size	1498	interior Color	Grey
Fuel	Petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Manual	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	02/07/2025	Inspection loc.	Dekra Ayvens		
-----------------	------------	-----------------	--------------	--	--



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Heating seats	✓
Tow	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element

Spare wheel (wheel & tyre)	✓
Load cover	✓

Technical Document

User manual	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Winter kit

Michelin 225/40/19 Winter 7.0 mm



Michelin 225/40/19 Winter 7.0 mm



Continental 225/40/19 Winter 7.5 mm



Continental 225/40/19 Winter 7.5 mm

Exterior

1



Part

Position

Damages

Severity

Repair mode

Alloy wheel 19"

Front left

Scratched

-

Lumpsum repair

2



Part

Position

Damages

Severity

Repair mode

Alloy wheel 19"

Back left

Scratched

-

Lumpsum repair

3



Part

Position

Damages

Severity

Repair mode

Wing

Back left

Chemical deposit

-

Lumpsum repair

4



Part

Position

Damages

Severity

Repair mode

Alloy wheel 19"

Back right

Scratched

-

Lumpsum repair

5



Part

Position

Damages

Severity

Repair mode

Door

Back right

Dented

Diameter (mm) > 20

Smart Repair

6



Part

Position

Damages

Severity

Repair mode

Alloy wheel 19"

Front right

Scratched

-

Lumpsum repair

7



Part

Position

Damages

Severity

Repair mode

Wing

Front right

Dent & Chips

Diameter (mm) > 20

Repair

8



Part

Position

Damages

Severity

Repair mode

Bumper

Front

Scratched

Length (cm) > 10

Repair

9



Part

Position

Damages

Severity

Repair mode

Bumper

Back

Scratched

Length (cm) > 10

Repair