



**Skoda Octavia: P048DL**

Vinnumber:	<b>TMBJR7NX9NY067049</b>	Versionname:	<b>Octavia 1.5 TSI E-Tec 110kW Business Edition Combi DSG</b>
First Registrationdate:	<b>16/02/2022</b>	Fiscalpower:	
Expertise Mileage:	<b>140882</b>	Power Kw:	<b>110</b>
Bodytype:		Body colour:	<b>Black Magic Metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Parking lot:	<b>203</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>No</b>		

**Options**

Number of keys total	<b>2</b>	Telephone equipment	
GPS		Central consol F	
Autom climate control		Luggage cover	
Windows electric F		Headlights Xenon/LED/Laser	
Radio multimedia		Front parking sensors	
		Rear parking sensors	
		Hook	

**Tyres**

Location	Position	Measures	Depth	Make	Type
Front	Left	205 / 60 / 16 / 92 / H / Aluminium	8,0 mm	Continental	Winter
	Right	205 / 60 / 16 / 92 / H / Aluminium	8,0 mm	Continental	Winter
Rear	Left	205 / 60 / 16 / 92 / H / Aluminium	7,0 mm	Continental	Winter
	Right	205 / 60 / 16 / 92 / H / Aluminium	7,0 mm	Continental	Winter

**Assistance equipment**

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>0</b>

**Seat cover RL, Stain, Cleaning**



**Outer door handle FL, Scratch(es), Repair and paint (complete)**



**Wing RL, Dent(s) and scratch(es), Repair and paint (complete)**





Bonnet, Dent(s), Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (partial)



Windscreen, Stone chip(s), Windscreen repair



Outer door handle FR, Scratch(es), Repair and paint (complete)



Wing RR, Dent(s), Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Roof, Dent(s), Paintless dent repair

