



Skoda Superb (KKL): 2AJP456

Vinnumber:	TMBJW7NP1M7054812	Versionname:	Superb Combi Ambition 1.4TSi iv 218pk/cv 5p DSG6
First Registrationdate:	16/04/2021	Fiscalpower:	
Expertise Mileage:	123392	Power Kw:	115
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	9800.0		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	2	Luggage cover	
GPS		Type of Tow bar	Tow bar collapsible
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

	215/55/17/94 V			
Summer tyres:	Fr.L.	Michelin: 3,1 mm	Fr.R.	Michelin: 3,8 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm
Tyre profile depth FL				3.1
Tyre profile depth FR				3.8
Tyre profile depth RL				5.0
Tyre profile depth RR				5.0
Tyre size FL				215/55 R 17 94 V
Tyre size FR				215/55 R 17 94 V
Tyre size RL				215/55 R 17 94 V
Tyre size RR				215/55 R 17 94 V
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				261
Tyre make FR				261
Tyre make RL				261
Tyre make RR				261

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	2		
Number of charging cables (rapid charge)	1		

Windscreen, Bad repair, Replace





Bonnet, Chemical polution, Repair and paint (complete)



Bumper F, Scratch(es), Repair and paint (complete)



Wing FL, Scratch(es), Acceptable



Door FL, Scratch(es), Acceptable



Wing RL, Bad repair, Repair and paint (complete)



Boot carpet, Stain, Cleaning



Boot lid covering R, Worn, Acceptable



Tailgate / Boot, Rust, Repair and paint (complete)



Bumper R, Scratch(es), Repair and paint (complete)



Rear spoiler, Chemical polution, Repair and paint (complete)



Alloy rim FR, Scratch(es), Acceptable



Wing RR, Scratch(es), Acceptable



Wing FR, Scratch(es), Acceptable



Door FR, Scratch(es), Acceptable



Door RR, Dent(s) and scratch(es), Repair and paint (complete)





Outer door handle FR, Scratch(es), Repair and paint (complete)



Bodywork, Not original part, Remove lettering



Roof, Chemical polution, Repair and paint (complete)

