



SKODA Superb

Superb Combi 1.4 TSI iV DSG

VIN NO TMBJW7NP4N7029842
Registration Number P4N7029842



MOT Date	Number of Owners	Number of Keys	Odometer Reading
2027-04-01	1	3	99193 km
Last Service	Last Service Mileage	First Registration Date	Country First Registered
2025-04-08	83469	2022-03-16	Germany

Inspection Report Summary

Customer	BCA Online	Report Number	P20251008110232
Inspection Date / Place	2025-10-08 / BCA Neuss	Cosmetic Grade	1

Vehicle Summary



Vehicle Condition	Runner	VAT Type	Qualifying
Fuel Type	Plug - in Hybrid Electric Vehicle Petrol	Road Worthy	Yes
Colour	Black	Engine Size (cc)	1395
Engine Size	1.4	No of Doors	5
Body Type	Stationwagon / Estate	Drive Train	Front
Seat Colour		No of Seats	5
Seat Covering Name	schwarz	Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	35
Gearbox Type	Automatic		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			









Equipment

Tow ball	Airbag Status	Anti-lock braking	Cabin Pre Heating
Digital Radio	Front parking sensors	Remote adjusting wing mirrors	Roof rails
Stability control	Leather steering wheel	Rear parking sensors	Adaptivecruisecontrol
Alloys wheels	Bluetooth telephone interface	Cruise control	Digitaldashboard
Heated wing mirrors	Remote central locking	Satellite navigation	Electrically folding wing mirrors


LED Headlamps

Equipment Details


Tow Ball Type	Pivoted	Air Conditioning	Dual Zone Climate Control
Alloy Wheel Size	17	Extra Wheel / Tyre Set	Winter Tyres - Alloy
Seat Heating	Front		

Cosmetic Damage

2 Schäden



1 Schäden




Component	Damage	Comments
1 Fender / Back Right	Paint / Scratch / Scuff	
2 Panel Filling / Back Right	Interior / Broken	
3 Hood	Bodywork / Dent / Dent	



1. Fender / Back Right
Paint / Scratch / Scuff -



2. Panel Filling / Back Right
Interior / Broken -



3. Hood
Bodywork / Dent / Dent -

Mechanical Condition

Control Lights

ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Airbag Warning Light	✓	Oil Pressure Warning Light	✓
Brake Warning Light	✓	Power Steering Warning Light	✓
Alternator / Battery	✓	No Dashboard Lights	✓
Display Defect	✓	Tire Pressure Monitoring System	✓

Engine

Engine Status / EML	✓	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	✓
--------------	----	---------------	---

Equipments Test

Electric Windows	✓	Navigation System	✓
Audio Equipment	✓	Parking Sensors / Cameras Functioning	✓

Hybrid/EV

Hybrid System Fault	✓
---------------------	---

Test Drive Inspection

Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	✓
Fume Quantity	✓	Power Loss	✓
Brake			
Brake System Anomaly	✓		
Steering Wheel			
Steering Noise / Anomaly	✓		
General			
Test Driven Status	✓		
✓ <i>No troubles detected, good condition or correct tests, according to vehicle age and mileage</i>			
! <i>Damages or malfunction detected that requires repairs by the buyer</i>			
NA <i>Not applicable</i>			
☐ <i>Not tested</i>			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)