


Vehicle details

VIN	TMBJW7NX0 MY188639	Brand	SKODA	Maintenance date	-
Licence Plate	N8-27-PK	Model	OCTAVIA COMBI 1.4 TSI iV PHEV DSG Business Edition	Maintenance mileage	-
Registration date	29/11/2021	Year	2021	Exterior Color	Grey Metallic
Odometer	197 189 km	Engine size	1395	interior Color	Grey
Fuel	Hybrid petrol	Body Type	-	Next technical inspection	-
Seats	-	Transmission	Automatic	CO2	-
Doors	5	Gears	-		

Inspection Details

Inspection date	08/09/2025	Inspection loc.	Ayvens Veghel
-----------------	------------	-----------------	---------------



Generic equipment

Automated air-conditioning	✓
Cruise control	✓
GPS system	✓
Alloy wheel rims	✓
Automatic Gearbox	✓
Metallic paint	✓
Central locking	✓
Electric windows	✓
Side rails	✓
Park Distance Control	✓
Audio System	✓
Led lighting	✓

Removable element


Spare wheel kit	✓
Load cover	✓
Vehicle charger	✓
Wireless charger	✓

Technical Document

User manual	✓
Warranty booklet	✓
Spare key	✓
Remote key	✓
Sat Nav CD ROM Software	✓

Tyres

Continental 225/45/18 All seasons
2.5 mm



Continental 225/45/18 All seasons
5.5 mm



Continental 225/45/18 All seasons
5.0 mm

Continental 225/45/18 All seasons
5.5 mm

Exterior

4



Part	Alloy wheel 18"
Position	Back right
Damages	Scratched
Severity	-
Repair mode	Lumpsum repair

5



Part	Sill
Position	Right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

6



Part	Door
Position	Back right
Damages	Dent & Chips
Severity	Diameter (mm) > 20
Repair mode	Repair

7



Part	Bumper
Position	Front
Damages	Scratched
Severity	Length (cm) > 10
Repair mode	Repair

8



Part	Roof
Position	-
Damages	Dented
Severity	Diameter (mm) > 20
Repair mode	Smart Repair

Interior damage

1



Part	Interior cleaning
Position	Front right
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

2



Part	Interior cleaning
Position	Back
Damages	Stained/dirty
Severity	-
Repair mode	Cleaning

3



Part	Interior tailgate lining
Position	Up
Damages	Scratched
Severity	-
Repair mode	Replace