

SKODA OCTAVIA COMBI IV

Vehicle information

License plate	NMP83H	Inspected by	A.H.
Year model	2021	Date of inspection	2025-03-06
Manuf. year/month	2020-12	City	Falkenberg
First day in traffic	2020-12	Keys	2
Colour	Vit	Service book	Elektronisk servicebok
Mileage	86 840 km	Latest service	2024-07-11
Fuel	Elhybrid	Mileage at the latest service	74 090 km
Transmission	DSG Sekventiell	Summer tires	18" alu-fälg 7/7/6/6
Engine effect	150 kW	Winter tires	alu-fälg odubbat 6/6/6/6

Damages

Location	Damage	Comments	Costs excluding VAT
Rims & Tires, Summer	Rim damage 2 wheel		270 €
Bumper, Rear	Small scratches, under 3 cm		70 €
Wing, Rear right	Dents below 30 mm		70 €
Bumper, Front	Chips, several		70 €
Bonnet	Chip		70 €
Glass, Windshield	Chip		30 €
Tak, Tak	Chip		70 €
Total excl. VAT			650 €

Images

[See all images in large format](#)


















Serviceprotokoll				SKODA
Ordernr 24916	Modellkod NX54VC	Registreringsnr NMP83H	Registrering 2021-02-26	
Chassinummer TMBJW7NX4MY091234	MMB DGEA	Mätarställning 74097	Servicerådgivare	
Modellkod OCT.COM iV STY TS150/1.4A6F	VMB TTT	Årsmodell 2021	Datum 11.07.2024	
Inspektion med oljebyte				
Vid bilmottagning		Ok/genomförd	Inte ok	Åtgärdat
Kontrollera connect-tjänsterna och aktivera verkstadsläget		☐	☒	☐
Bilen invändigt		Ok/genomförd	Inte ok	Åtgärdat
Serviceintervallindikering: Nollställa		☒	☐	☐
Signalhorn: Kontrollera funktionen		☒	☐	☐







Fälgar & Däck Sommar Fälgskada 2 hjul 3 000 kr



Stötfångare Bak Repor små, under 3 cm 800 kr



Skärm Höger bak Bucklor under 3 cm 800 kr



Stötfångare Fram Stenskott flertal 800 kr



Motorhuv Stenskott 800 kr



Glas Vindruta Stenskott 300 kr



Tak Tak Stenskott 800 kr





