



Skoda Octavia (UKL): 2AVK801

Vinnumber:	TMBJW7NX8MY173791	Versionname:	Octavia Combi Clever 1.4TSi iV 204pk/cv 5p DSG6
First Registrationdate:	4/08/2021	Fiscalpower:	
Expertise Mileage:	144341	Power Kw:	110
Bodytype:		Type of rims (mounted)	Aluminium
Gearbox:	Automatic		
Transmission:			
Fueltype:			
Maintenance	OK		
Maintenance	10100 km - 309 km		
Battery functioning	Yes		
Type of rims (mounted)	Aluminium		
Certificate of Conformity	Yes		
Category	Passenger Car		
Registration Certificate Car (BE)	Yes		

Options

Number of keys total	3	Luggage cover	
GPS		Type of Tow bar	Tow bar removable
Type of Maintenance book	Digital maintenance		
Type of GPS storage	HD		

Tyres

225/45/18/91 Y				
Summer tyres:	Fr.L.	Goodyear: 6 mm	Fr.R.	Goodyear: 6 mm
	Re.L.	Goodyear: 6 mm	Re.R.	Goodyear: 6 mm
Tyre profile depth FL				6.0
Tyre profile depth FR				6.0
Tyre profile depth RL				6.0
Tyre profile depth RR				6.0
Tyre size FL				225/45 R 18 91 Y
Tyre size FR				225/45 R 18 91 Y
Tyre size RL				225/45 R 18 91 Y
Tyre size RR				225/45 R 18 91 Y
Tyre type FL				Summer
Tyre type FR				Summer
Tyre type RL				Summer
Tyre type RR				Summer
Tyre make FL				259
Tyre make FR				259
Tyre make RL				259
Tyre make RR				259

Assistance equipment

Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	1		

Ignition key, Not functioning (well), Acceptable



Bonnet, Stone chip(s), Acceptable



Bumper F, Stone chip(s), Acceptable




Door FL, Scratch(es), Acceptable



Door RL, Dent(s) and scratch(es), Acceptable



Wing RL, Dent(s) and scratch(es), Acceptable



Step L, Scratch(es), Acceptable



Charging cable (normal), Missing, Check



Internal boot lining L, Scratch(es), Acceptable



Internal boot lining R, Scratch(es), Acceptable



Boot lid covering R, Scratch(es), Acceptable



Bumper R, Scratch(es), Acceptable



Alloy rim RR polished, Scratch(es), Repair and paint (complete)



Step R, Scratch(es), Acceptable



Alloy rim FR polished, Scratch(es), Repair and paint (complete)



Outer sill R, Deformed / Strained, Repair and paint (complete)

