



### Skoda Superb: K184TF

Vinnnumber:	<b>TMBJW9NP7M7046029</b>	Versionname:	<b>Superb 1.4 TSI PHEV 160kW Business Edition Plus combi DSG</b>
First Registrationdate:	<b>4/03/2021</b>	Fiscalpower:	
Expertise Mileage:	<b>84040</b>	Power Kw:	<b>115</b>
Bodytype:		Body colour:	<b>Race Blue metallic</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Type of rims (mounted):	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Parking lot:	<b>994</b>
Number of seats:	<b>5</b>		
Type of rims (mounted):	<b>Aluminium</b>		
Maintenance needed:	<b>Yes</b>		

### Options

Number of keys total	<b>2</b>	Telephone equipment
GPS		Lining semi-leather
Autom climate control		Lining Alcantara
Windows electric F		Central consol F
Radio multimedia		Luggage cover
		Headlights Xenon/LED/Laser
		Front parking sensors
		Rear parking sensors

### Tyres

Location	Position	Measures	Depth	Make	Type
Front	Left	235 / 15 / 18 / 98 / V / Aluminium	5,6 mm	Michelin	Winter
	Right	235 / 15 / 18 / 98 / V / Aluminium	5,7 mm	Michelin	Winter
Rear	Left	235 / 15 / 18 / 98 / V / Aluminium	6,9 mm	Michelin	Winter
	Right	235 / 15 / 18 / 98 / V / Aluminium	6,1 mm	Michelin	Winter

### Assistance equipment

Number of charging cables (normal)	<b>0</b>
Number of charging cables (rapid charge)	<b>1</b>

### Service, Maintenance, Execute



### Door FL, Dent(s) and scratch(es), Repair and paint (complete)



### Wing RL, Scratch(es), Repair and paint (complete)




Door RL, Scratch(es), Repair and paint (complete)



Outside rear-view mirror housing L, Scratch(es), Replace and paint



Windscreen, Stone chip(s), Windscreen repair




Bonnet, Chemical polution, Polish



Bumper F, Scratch(es), Repair and paint (complete)



Door RR, Dent(s) and scratch(es), Repair and paint (complete)



Bumper R, Dent(s) and scratch(es), Repair and paint (complete)





Roof, Chemical polution, Polish

