



SKODA Yeti

Yeti 2.0 TDI

VIN NO TMBLD75L4B6053684

Registration Number L4B6053684



MOT Date



Last Service

2019-10-30

Number of Owners



Last Service Mileage

119461

Number of Keys



First Registration Date

2011-05-10

Odometer Reading



Country First Registered



197775 km

Inspection Report Summary

Customer	BCA Online	Report Number	P20250825084700
Inspection Date / Place	2025-08-25 / ARS Altmann AG Wolnzach	Cosmetic Grade	5


Vehicle Summary


Vehicle Condition	Runner	VAT Type	Margin
Fuel Type	Diesel	Road Worthy	Yes
Colour	Grey	Engine Size (cc)	1968
Engine Size	2.0	No of Doors	5
Body Type	SUV	Drive Train	All-Wheel-Drive permanent
Seat Colour		No of Seats	5
Seat Covering Name		Seat Covering	Cloth
Charging Cables		NEDC CO2 Rating (q/km)	157
Gearbox Type	Manual		

Vehicle History & Documents

Service Book Available	Present	Next Service Mileage	km
Previous Usage		Imported	No
Manufacturer Warrenty			







Equipment

USB Socket	Alloys wheels	Auxiliary Socket	Diesel particulate filter
Remote adjusting wing mirrors	Roof rails	Central locking	Radio
Airbag Status	Anti-lock braking	Cruise control	Heated wing mirrors
Remote central locking	Stability control	Leather steering wheel	Rear parking sensors

Equipment Details


Air Conditioning	Dual Zone Climate Control	Alloy Wheel Size	17
Extra Wheel / Tyre Set	Winter Tyres - Alloy	Seat Heating	Front

Wheels & Tyres


Right Front Tyre Depth	3	Left Front Tyre Depth	3
Right Rear Tyre Depth	4	Left Rear Tyre Depth	4
Extra Wheel - 1 Tyre Depth	4	Extra Wheel - 2 Tyre Depth	4
Extra Wheel - 3 Tyre Depth	4	Extra Wheel - 4 Tyre Depth	4

Cosmetic Damage

34 Schäden



1 Schäden



Component		Damage	Comments
1	Door / Front Left	Paint / Poor Previous Repair	
2	Door / Back Left	Paint / Poor Previous Repair	
3	Tailgate	Paint / Poor Previous Repair	
4	Side Panel / Back Right	Paint / Poor Previous Repair	
5	Door / Back Right	Paint / Poor Previous Repair	
6	Door / Front Right	Paint / Poor Previous Repair	
7	Wing Repeater / Left	Bodywork / Dent / Dent	
8	Door / Back Left	Bodywork / Dent / Dent	
9	Roof	Bodywork / Dent / Dent	
10	Roof	Bodywork / Dent / Dent	
11	Door / Front Right	Bodywork / Dent / Dent	
12	Door / Back Right	Bodywork / Dent / Dent	
13	Bumper / Front	Paint / Scratch / Scuff	

14	Wing Repeater / Left	Paint / Scratch / Scuff
15	Door / Front Left	Paint / Corrosion
16	Door / Front Left	Paint / Scratch / Scuff
17	Door / Front Left	Paint / Scratch / Scuff
18	Door / Back Left	Paint / Scratch / Scuff
19	Side Panel / Back Left	Paint / Corrosion
20	Pillar / Back Left	Paint / Scratch / Scuff
21	Bumper / Back	Paint / Scratch / Scuff
22	Bumper / Back	Paint / Scratch / Scuff
23	Tailgate	Paint / Scratch / Scuff
24	Tailgate	Paint / Corrosion
25	Luggage Space Cover / Back	Interior / Missing
26	Side Panel / Back Right	Paint / Corrosion
27	Door / Back Right	Paint / Scratch / Scuff
28	Door / Back Right	Bodywork / Breakage / Hole
29	Pillar / Back Right	Paint / Scratch / Scuff
30	Door / Front Right	Paint / Corrosion
31	Door / Front Right	Paint / Scratch / Scuff
32	Pillar / Front Right	Bodywork / Breakage / Hole
33	Mirror Shell / Front Right	Paint / Scratch / Scuff
34	Rim / Front Right	Out of Bodywork / Scratch
35	Bumper / Front	Paint / Scratch / Scuff



1. Door / Front Left
Paint / Poor Previous Repair -



2. Door / Back Left
Paint / Poor Previous Repair -



3. Tailgate
Paint / Poor Previous Repair -



4. Side Panel / Back Right
Paint / Poor Previous Repair -




5. Door / Back Right
Paint / Poor Previous Repair -




6. Door / Front Right
Paint / Poor Previous Repair -




7. Wing Repeater / Left
Bodywork / Dent / Dent -




8. Door / Back Left
Bodywork / Dent / Dent -




9. Roof
Bodywork / Dent / Dent -



10. Roof
Bodywork / Dent / Dent -



11. Door / Front Right
Bodywork / Dent / Dent -



12. Door / Back Right
Bodywork / Dent / Dent -



13. Bumper / Front
Paint / Scratch / Scuff -



14. Wing Repeater / Left
Paint / Scratch / Scuff -



15. Door / Front Left
Paint / Corrosion -



16. Door / Front Left
Paint / Scratch / Scuff -



17. Door / Front Left
Paint / Scratch / Scuff -



18. Door / Back Left
Paint / Scratch / Scuff -



19. Side Panel / Back Left
Paint / Corrosion -



20. Pillar / Back Left
Paint / Scratch / Scuff -



21. Bumper / Back
Paint / Scratch / Scuff -



22. Bumper / Back
Paint / Scratch / Scuff -



23. Tailgate
Paint / Scratch / Scuff -



24. Tailgate
Paint / Corrosion -



25. Luggage Space Cover / Back Interior / Missing -



26. Side Panel / Back Right Paint / Corrosion -




27. Door / Back Right Paint / Scratch / Scuff -



28. Door / Back Right Bodywork / Breakage / Hole -



29. Pillar / Back Right Paint / Scratch / Scuff -




30. Door / Front Right Paint / Corrosion -



31. Door / Front Right
Paint / Scratch / Scuff -



32. Pillar / Front Right
Bodywork / Breakage / Hole -



33. Mirror Shell / Front Right
Paint / Scratch / Scuff -



34. Rim / Front Right
Out of Bodywork / Scratch -



35. Bumper / Front
Paint / Scratch / Scuff -

Mechanical Condition

Control Lights

Display Defect	✓	Service Light	✓
ABS Warning Light	✓	ESP Fault/Traction Control Malfunction Light	✓
Diesel Particulate Filter Light	✓	Airbag Warning Light	✓
Oil Pressure Warning Light	✓	Brake Warning Light	✓
Power Steering Warning Light	✓	Alternator / Battery	✓
No Dashboard Lights	!		

Equipments Test

Central Locking	✓	Main & Spare Keys Functioning	✓
Electric Windows	✓	Audio Equipment	✓
Parking Sensors / Cameras Functioning	✓	AC / Heating System	✓

Engine

Engine Status / EML	!	Engine Leak Visible	✓
Engine Starts	✓		

Gearbox

Gear Box	✓
----------	---

Levels

Brakes Fluid	NA	Coolant Fluid	!
--------------	----	---------------	---

Test Drive Inspection

Steering Wheel			
Steering Noise / Anomaly		✓	
Engine			
Engine Noise	✓	The Gears Scratch / Skip / Abnormal Operation	!
Fume Quantity	✓	Power Loss	✓
Clutch			
Clutch Functioning		!	
Brake			
Brake System Anomaly		!	
General			
Test Driven Status		✓	
✓ No troubles detected, good condition or correct tests, according to vehicle age and mileage			
! Damages or malfunction detected that requires repairs by the buyer			
NA Not applicable			
= Not tested			

Disclaimer

Please also note the "UserGuide condition report", which shows the scope of the vehicle description.

[User Guide](#)